# molex®

# **ENGINEERING SPECIFICATION**

## **INSTALLATION INSTRUCTION SHEETS**

#### 1.0 SCOPE

This specification consists of installation instructions for the Self Contained Power Connector for 3-wire cable with ground applications.

# 2.0 PURPOSE

To define material number system for the above instructions.

#### 3.0 REFERENCE MATERIAL NUMBERS

See pages 2-3 for the actual instruction sheets. These pages can be used as originals.

#### 4.0 DEFINITIONS

Not applicable.

#### 5.0 PROCEDURES

Place one (1) instruction sheet in the smallest unit container.

## **6.0 IMPLEMENTATION**

January 24, 2006

TEMPLATE FILENAME: ENGINEERING_SPEC[SIZE_A](V.1).DOC						
SD-19401-002		E. THRODAHL	J. MACNEIL	J. MACNEIL		
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPROVED BY:		
	DATE: 2010 / 10 / 13	FOR 3 WIRE CABLE WITH GROUND APPLICATIONS			1013	
F	EC No: WNA2011-0191	INSTA	1 of 3			
REVISION:	ECR/ECN INFORMATION:	TITLE: SELF CONTAINED POWER CONNECTOR SHEET No.				

# COC-2 Self Contained Power Connector Installation Instructions For 3 Wire Cable with Ground Applications

The 3-circuit connector is used to splice solid nonmetallic cable 14/3 and 12/3 with ground.

Wire				Housing
Range		Optional	Optional Bench	
AWG	Order No.	Hand Tool	Arbor Press	Color
12-14	19401-1000 (COC-2)	19285-0074	64006-0200	White







#### Reference Information

UL File Number: E182087 CSA File Number: LR18689-C53 NEC Article: 550, 551, and 545

HUD Section: 3280.801

Current: 20A Voltage: 600V





## **Installation Procedure:**

- 1. Carefully strip and prepare the wires to the configuration as shown in **Figure 1** using helpful hints shown in photographs of **Figure 2**.
- 2. Hold the clear strain-relief cover with bottom facing upward as shown in Figure 3.
- 3. Lay wires into locator slots, making sure the red and black wires are placed into locator slots with the polarization stop as shown in **Figure 3.** If cable is flat, squeeze into round shape to fit.
- **4.** Press the cable sheath into the integral strain relief slot as shown in **Figure 3**. Trimming of center wires and possibly others will be necessary. Wires must not extend beyond the stops as shown in Figure 4!
- **5.** While holding the strain relief cover, position the housing's hinge posts into the hinge slots and press down until both lock into place as shown in **Figure 4.**
- 6. Close the strain relief cover and housing by hand. Place the connector assembly into Molex tool (preferred) as shown in Figure 5. Squeeze the tool until the connector bottoms out and the locking latches engage on both sides. OR alternately, squeeze the top and bottom closed with tongue and groove pliers as shown in Figure 5.1. Pliers must be a minimum of 10" long. Squeeze firmly on both sides, squarely across the connector between ribs A and B (labeled in Figure 5.1) to ensure wires seat completely into slots.
- 7. Inspect the connector to ensure the wires have been properly engaged into the housing assembly contacts. A properly terminated wire is fully seated into its proper slots with no significant bow of the cover. If the wires extend past the insulation stops, the wires must be re-terminated with a NEW CONNECTOR. Once the cover has been closed the connector cannot be re-used. Failure to comply with this procedure may result in the failure of the connector.
- 8. Mating and un-mating the completed connector is illustrated in Figure 6.

