

SIERRA WIRELESS PRODUCT BULLETIN

CONFIDENTIAL - DO NOT DISTRIBUTE EXTERNALLY EXCEPT TO CUSTOMERS EXPLICITLY NOTED BELOW

OVERVIEW

DATE ISSUED:	Dec 22, 2021	TRACKING NUMBER:	4134914
ISSUED BY:	IoT Solutions Product Management		
PRODUCTS AFFECTED:	WP7702, FX30 LTE-M, FX30S LTE-M		
SKUS AFFECTED:	See "Details of Change" for SKUs affected		
BULLETIN:	Transition to new FW and deprecation of SKUs		
URGENCY:	High		
EFFECTIVE DATE:	Effective Immediately		
FOR DISTRIBUTION TO:	All WP7702 and FX30 customers and their partners		

Summary

Sierra Wireless is announcing the commercial availability of its latest WP7702 and FX30 software release, version 15. This version is a major update to the Legato application framework and Linux kernel. Updating the Legato framework and Linux kernel is important to keep the products secure with the latest security updates from Sierra and the Linux community. There are no impact to regulatory or carrier certification. No certification updates are needed.

A beta version of Release 15 is currently available on Leaf for early evaluation and feedback. For more information on how to use Leaf. please refer to Legato, io.

All SKUs using the legacy FW versions will be deprecated 3 months from the date of this notice and no new orders for legacy SKUs will be accepted after the effective date. These SKUs will be replaced by new ones using the Release 15.

Details of Change

The following table summarizes the legacy SKUs that are being replaced with new ones running Release 15

Legacy SKUs	Replacement SKUs		
WP7702			
1103530 WP7702, GENERIC, GENERIC, R9	1104918 WP7702, GENERIC, GENERIC, R15.0.3; R2C		
1104214 WP7702, GENERIC, GENERIC/AT&T/VERIZON, R11			
1104405 WP7702, OCTAVE, SIERRA/GENERIC, R13	1105033 WP7702, OCTAVE, SIERRA, R15.0.3; R2C		
FX30 CAT-M			
1104534 FX30, SWIR, GENERIC, R9.1.1.013	1105031 FX30, GENERIC, SIERRA, R15.0.3; R2C		
1104536 FX30, SWIR, SIERRA, R9.1.1.013, SWIR 2FF			
1104736 FX30, SWIR, GENERIC, R11.0.0.007			
1104738 FX30, SWIR, SIERRA, R11.0.0.007, SWIR 2FF			
1104665 FX30, OCTAVE, OCTAVE, R11.0.0.005, SWIR 2FF	1104899 FX30, OCTAVE, OCTAVE, R15.0.3; R2C		
1104808 FX30, OCTAVE, OCTAVE, R11.0.0.005, ATT ECC	1104896 FX30, OCTAVE, OCTAVE, R15.0.3; ATT ECC		

FX30S CAT-M			
1104542 FX30S, SWIR, GENERIC, R9.1.1.013	1105032 FX30S, GENERIC, SIERRA, R15.0.3; R2C		
1104544 FX30S, SWIR, SIERRA, R9.1.1.013, SWIR 2FF			
1104737 FX30S, SWIR, GENERIC, R11.0.0.007			
1104739 FX30S, SWIR, SIERRA, R11.0.0.007, SWIR 2FF			
1104666 FX30S, OCTAVE, OCTAVE, R11.0.0.005; SWIR 2FF	1104900 FX30S, OCTAVE, OCTAVE, R15.0.3; R2C		
1104809 FX30S, OCTAVE, OCTAVE, R11.0.0.005, ATT ECC	1104897 FX30S, OCTAVE, OCTAVE, R15.0.3; ATT ECC		

Effective Dates

This change is effective immediately and customers should transition to Release 15 and the replacement SKUs as soon as possible.

No new orders will be accepted for the legacy SKUs. Any existing orders with <u>requested shipment date</u> on or after **April 1**, **2022** will need to be updated to use the replacement SKUs.

More information

For more information, please contact your Sierra Wireless sales/technical support person.