

1 Products affected

Product hierarchy no. *			archy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Туре				
			0000002361	See list below	Connectors	1621	


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected	st of part numbers affected					
6163.0001	6163.0002	6163.0003	6163.0004			
6163.0005	6163.0006	6163.0007	6163.0009			

2 Type of change

Backside of flange with ribs and less material

3 Detailed description of change



4 Reason of change

To improve the moulding process and to avoid flow lines

5 Release date

The change takes effect in ww 09/2021 (Date code 2109 or higher on label).

6 Impact of change and recommended action

Form Yes Less material and new a rib construction on the backside of flange

Fit No No change for dimension Function No No change in function

Manufacturing No No change for manufacturing site

Label No No change on label Packaging No No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks	
Data Sheet 1621		

Product Change Notification					PCN 1621			
owner	creation date	release date	released by	change order no	rev	page	D40 055 745	
kesslema	01.03.2021	01.03.2021	muehlema	2021558	Α	1 of 1	D10-055-715	