



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000986N

DATE: 20-Mar-2020

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------|--------------------|-------------------------|-----------------|--------------------|--|
| Reactivation | MAX11290EWX+ | N/A | | | Part reactivated from prior notice: M000973I |
| Reactivation | MAX11290EWX+T | N/A | | | Part reactivated from prior notice: M000973I |
| Reactivation | MAX14602ETA+ | N/A | | | Part reactivated from prior notice: M000969I |
| Reactivation | MAX15118EWI+ | N/A | | | Part reactivated from prior notice: M000965I |
| Reactivation | MAX15118EWI+T | N/A | | | Part reactivated from prior notice: M000965I |
| Reactivation | MAX16005ETE+T | N/A | | | Part reactivated from prior notice: M000969I |
| Reactivation | MAX17710G+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX17710GB+ | N/A | | | Part reactivated from prior notice: M000965I |
| Reactivation | MAX19793ETX+ | N/A | | | Part reactivated from prior notice: M000969I |
| Reactivation | MAX19793ETX+T | N/A | | | Part reactivated from prior notice: M000969I |
| Discontinuance | MAX186DMLP-WM0A | MAX186DMLP/M0A | 20-Mar-2020 | 16-Sep-2020 | The part was not released |
| Discontinuance | MAX6381XR25D2+TGA8 | N/A | 20-Mar-2020 | 16-Sep-2020 | The part was not released |
| Discontinuance | MAX6418UK29+TG51 | N/A | 20-Mar-2020 | 16-Sep-2020 | The part was not released |
| Discontinuance | MAX6834HXR3D3+TGC1 | N/A | 20-Mar-2020 | 16-Sep-2020 | The part was not released |
| Discontinuance | MAX810TEXR+TG05 | N/A | 20-Mar-2020 | 16-Sep-2020 | The part was not released |
| Discontinuance | MAX810TEXR+TG51 | N/A | 20-Mar-2020 | 16-Sep-2020 | The part was not released |
| Discontinuance | TSC427MJA | N/A | 20-Mar-2021 | 16-Sep-2021 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Apr-2020