



Cypress Semiconductor, 198, Champion Court, San Jose, CA 95134. Tel: (408)943-2600

PRODUCT INFORMATION NOTIFICATION

PIN: PIN145276

Date: March 13, 2014

Subject: Addendum to PIN 135258 - Qualification of JCET as an additional Test and Finish Location for Cypress Products

To: PCN ADMINISTRATOR
CYPRESS PCN ADMIN
pcn_adm@cypress.com

Change Type: Major


Description of Change:

Cypress released PIN 135258 to inform customers of the qualification done on package-level Test and Finish manufacturing operations at Jiangsu Changjiang Electronics Technology Co., Ltd (JCET) in China for Cypress products that are currently being assembled at JCET and tested at King Yuan Electronics Co., Ltd., (KYES) Taiwan and ChipMOS Technologies Inc., Hsinchu, Taiwan. There will not be any changes to the tester platforms, test program coverage or methodologies. This addendum covers 221 additional parts that are being qualified for Test and Finish at JCET.

JCET is the largest provider of independent semiconductor manufacturing services in assembly and test in China. Their assembly facility in Changjiang, China is already a qualified assembly site for Cypress products. This qualification will enable these products to be assembled, tested, finished and shipped directly to Cypress customers from one subcontractor facility. This qualification will allow Cypress to leverage JCET's manufacturing expertise and quality focus. This in turn also provides the means for Cypress to continue to meet its customers' IC testing needs as well as delivery commitments in dynamic, changing market conditions. JCET is certified on several international quality standards: ISO / TS16949: 2009, ANSI/ESD S20.20:2007, IECQ QC 080000:2005, ISO14001 and OHSAS18001.

Benefit of Change:

This change will provide a turnkey solution for these products that are being manufactured in Cypress' subcontractors. This will provide a faster delivery of products to Cypress' customers.



Affected Part Numbers: 876 (655 from PIN135258 plus 221 from this addendum notice)
Affected Parts: Please see the attached file for the list of parts affected by this notice.

Customer Part Numbers Affected: N/A
Affected Parts: N/A

Qualification Status:

The qualification reports for Advantest test-platform, Nextest test-platform and TSOPII 44L Finish qualification can be found as an attachment to this notification or by visiting www.cypress.com, typing the QTP number in the keyword search window. The qualification reports for other package types and test-platforms will be available in April 2014 to June 2014.

Please refer to table below for the complete qualification schedules. Note that the schedules are estimated dates based on current projections, and are subject to change.

Tester Platform	QTP Number	Expected Date of Completion
ADVANTEST	133704	Completed
VERSA 2104	133806	April 2014 to June 2014
VERSA 3308	133806	April 2014 to May 2014
NEXTEST	133805	Completed
FINISH PROCESS TSOPII 44L	133803	Completed
FINISH PROCESS (TQFP/SNC)	134905	March 2014
FINISH PROCESS (SOJ 300mils)	134905	March 2014
FINISH PROCESS (STSOP)	140909	April 2014
FINISH PROCESS (SOIC)	140910	April 2014
FINISH PROCESS (SSSOP)	140911	May 2014

Approximate PIN Implementation Date:

Implementation started in December 2013 and is expected to be complete by June 2014. Shipping directly from JCET to Cypress customers is expected to start in April 2014.

Anticipated Impact:

Products that will be tested at JCET China will be completely compatible with existing product from a functional, parametric, and quality performance perspective.

Cypress also recommends that customers take this opportunity to review these changes against current application notes, system design considerations and customer environment conditions to assess impact (if any) to their application.

Method of Identification:

Cypress maintains traceability of product to wafer level, including wafer fabrication location, through the lot number marked on the package.

Response Required:

This is an information announcement only. No response is required

For additional information regarding this change, contact your local sales representative or contact the PCN Administrator at pcn_adm@cypress.com.

Sincerely,
Cypress PCN Administration

Item	Marketing Part Number	Remarks
1	CY62126ESL-45ZSXI	Part affected by Addendum notice
2	CY62126ESL-45ZSXIT	Part affected by Addendum notice
3	CY62126EV30LL-45ZSXI	Part affected by Addendum notice
4	CY62126EV30LL-45ZSXIT	Part affected by Addendum notice
5	CY62137FV30LL-45ZSXIT	Part affected by Addendum notice
6	CY62148ESL-55ZAXI	Part affected by Addendum notice
7	CY62148ESL-55ZAXIT	Part affected by Addendum notice
8	CY62157DV30LL-55ZSXI	Part affected by Addendum notice
9	CY62157DV30LL-55ZSXIT	Part affected by Addendum notice
10	CY62157EV30LL-45ZSXIT	Part affected by Addendum notice
11	CY7C1010DV33-10ZSXI	Part affected by Addendum notice
12	CY7C1010DV33-10ZSXIT	Part affected by Addendum notice
13	CY7C1018DV33-10VXIT	Part affected by Addendum notice
14	CY7C1021BN-12ZXC	Part affected by Addendum notice
15	CY7C1021BN-12ZXC	Part affected by Addendum notice
16	CY7C1021BN-15ZXI	Part affected by Addendum notice
17	CY7C1021BN-15ZXC	Part affected by Addendum notice
18	CY7C1021BNL-15ZXI	Part affected by Addendum notice
19	CY7C1021BNL-15ZXC	Part affected by Addendum notice
20	CY7C1041CV33-10ZXC	Part affected by Addendum notice
21	CY7C1041CV33-8ZSXI	Part affected by Addendum notice
22	CY7C1041CV33-8ZSXIT	Part affected by Addendum notice
23	CY7C1041LV33-10ZSXI	Part affected by Addendum notice
24	CY7C1041LV33-10ZSXIT	Part affected by Addendum notice
25	CY7C1049CV33-10ZXC	Part affected by Addendum notice
26	CY7C1049CV33-10ZXC	Part affected by Addendum notice
27	CY7C1325G-133AXC	Part affected by Addendum notice
28	CY7C1325G-133AXCT	Part affected by Addendum notice
29	CY7C1325H-133AXI	Part affected by Addendum notice
30	CY7C1329H-133AXC	Part affected by Addendum notice
31	CY7C1329H-133AXCT	Part affected by Addendum notice
32	CY7C1338G-100AXC	Part affected by Addendum notice
33	CY7C1338G-100AXCT	Part affected by Addendum notice
34	CY7C1350G-133AXC	Part affected by Addendum notice
35	CY7C1350G-133AXCT	Part affected by Addendum notice
36	CY7C1350G-133AXI	Part affected by Addendum notice
37	CY7C1350G-133AXIT	Part affected by Addendum notice
38	CY7C1351G-100AXC	Part affected by Addendum notice
39	CY7C1351G-100AXCT	Part affected by Addendum notice
40	CY7C1351G-133AXC	Part affected by Addendum notice
41	CY7C1352G-133AXC	Part affected by Addendum notice
42	CY7C1352S-133AXC	Part affected by Addendum notice
43	CY7C1352S-133AXI	Part affected by Addendum notice
44	CY7C1353G-100AXC	Part affected by Addendum notice
45	CY7C1353G-100AXCT	Part affected by Addendum notice
46	CY7C1353S-100AXC	Part affected by Addendum notice
47	CY7C1353S-100AXCT	Part affected by Addendum notice
48	CY7C1354CV25-166AXC	Part affected by Addendum notice
49	CY7C1354CV25-166AXCT	Part affected by Addendum notice
50	CY7C1354CV25-200AXC	Part affected by Addendum notice
51	CY7C1354S-166AXC	Part affected by Addendum notice
52	CY7C1360C-166AJXC	Part affected by Addendum notice

53	CY7C1360C-166AJXCT	Part affected by Addendum notice
54	CY7C1360C-166AXC	Part affected by Addendum notice
55	CY7C1360C-166AXCT	Part affected by Addendum notice
56	CY7C1360C-166AXI	Part affected by Addendum notice
57	CY7C1360C-200AJXC	Part affected by Addendum notice
58	CY7C1360C-200AXC	Part affected by Addendum notice
59	CY7C1360C-200AXCT	Part affected by Addendum notice
60	CY7C1360S-166AXI	Part affected by Addendum notice
61	CY7C1360S-200AXI	Part affected by Addendum notice
62	CY7C1362S-200AXC	Part affected by Addendum notice
63	CY7C1363D-133AXI	Part affected by Addendum notice
64	CY7C1363S-133AXC	Part affected by Addendum notice
65	CY7C1364CV33-166AXC	Part affected by Addendum notice
66	CY7C1365CV33-133AXC	Part affected by Addendum notice
67	CY7C1384D-166AXI	Part affected by Addendum notice
68	CY7C1385D-133AXI	Part affected by Addendum notice
69	CY7C1440AV33-167AXC	Part affected by Addendum notice
70	CY7C1440AV33-250AXC	Part affected by Addendum notice
71	CY7C1440AV33-250AXI	Part affected by Addendum notice
72	CY7C1440SV33-167AXC	Part affected by Addendum notice
73	CY7C1441AV33-133AXC	Part affected by Addendum notice
74	CY7C1441AV33-133AXI	Part affected by Addendum notice
75	CY7C1441AV33-133AXIT	Part affected by Addendum notice
76	CY7C1444AV33-167AXC	Part affected by Addendum notice
77	CY7C1444AV33-250AXI	Part affected by Addendum notice
78	CY7C1460AV25-167AXC	Part affected by Addendum notice
79	CY7C1460AV25-167AXCT	Part affected by Addendum notice
80	CY7C1460AV25-250AXC	Part affected by Addendum notice
81	CY7C1460AV33-167AXC	Part affected by Addendum notice
82	CY7C1460AV33-167AXCT	Part affected by Addendum notice
83	CY7C1460AV33-167AXI	Part affected by Addendum notice
84	CY7C1460AV33-200AXC	Part affected by Addendum notice
85	CY7C1460AV33-200AXCT	Part affected by Addendum notice
86	CY7C1460AV33-250AXC	Part affected by Addendum notice
87	CY7C1460AV33-250AXI	Part affected by Addendum notice
88	CY7C1460SV25-167AXC	Part affected by Addendum notice
89	CY7C1460SV25-167AXCT	Part affected by Addendum notice
90	CY7C1460SV33-200AXC	Part affected by Addendum notice
91	CY7C1461AV33-133AXC	Part affected by Addendum notice
92	CY7C1461AV33-133AXCT	Part affected by Addendum notice
93	CY7C1461AV33-133AXI	Part affected by Addendum notice
94	CY7C1461SV33-133AXC	Part affected by Addendum notice
95	CY7C1461SV33-133AXCT	Part affected by Addendum notice
96	CY7C1462AV25-200AXC	Part affected by Addendum notice
97	CY7C1462AV25-200AXCT	Part affected by Addendum notice
98	CY7C1462AV33-167AXC	Part affected by Addendum notice
99	CY7C1462AV33-167AXCT	Part affected by Addendum notice
100	CY7C1462AV33-200AXI	Part affected by Addendum notice
101	CY7C1462BV25-250AXC	Part affected by Addendum notice
102	CY7C1463AV33-133AXC	Part affected by Addendum notice
103	CY7C1463BV33-133AXI	Part affected by Addendum notice
104	CY7C1470BV25-167AXC	Part affected by Addendum notice
105	CY7C1470BV25-167AXCT	Part affected by Addendum notice

106	CY7C1470BV25-200AXC	Part affected by Addendum notice
107	CY7C1470BV25-200AXI	Part affected by Addendum notice
108	CY7C1470BV25-250AXC	Part affected by Addendum notice
109	CY7C1470BV25-250AXI	Part affected by Addendum notice
110	CY7C1470BV33-167AXC	Part affected by Addendum notice
111	CY7C1470BV33-167AXCT	Part affected by Addendum notice
112	CY7C1470BV33-167AXI	Part affected by Addendum notice
113	CY7C1470BV33-200AXC	Part affected by Addendum notice
114	CY7C1470BV33-200AXI	Part affected by Addendum notice
115	CY7C1470V25-200AXC	Part affected by Addendum notice
116	CY7C1470V33-167AXC	Part affected by Addendum notice
117	CY7C1470V33-167AXI	Part affected by Addendum notice
118	CY7C1470V33-200AXC	Part affected by Addendum notice
119	CY7C1471BV25-133AXI	Part affected by Addendum notice
120	CY7C1471BV33-133AXC	Part affected by Addendum notice
121	CY7C1471BV33-133AXCT	Part affected by Addendum notice
122	CY7C1471V25-133AXC	Part affected by Addendum notice
123	CY7C1471V33-133AXC	Part affected by Addendum notice
124	CY7C1472BV25-200AXC	Part affected by Addendum notice
125	CY7C1472BV25-200AXCT	Part affected by Addendum notice
126	CY7C1472BV33-167AXI	Part affected by Addendum notice
127	CY7C1472V25-200AXC	Part affected by Addendum notice
128	CY7C1472V33-200AXC	Part affected by Addendum notice
129	CY7C1473BV33-133AXC	Part affected by Addendum notice
130	CY7C1480BV25-167AXC	Part affected by Addendum notice
131	CY7C1480BV33-167AXI	Part affected by Addendum notice
132	CY7C1480BV33-200AXC	Part affected by Addendum notice
133	CY7C1480V33-167AXC	Part affected by Addendum notice
134	CY7C1480V33-200AXC	Part affected by Addendum notice
135	CY7C1481BV25-133AXI	Part affected by Addendum notice
136	CY7C1481BV33-133AXI	Part affected by Addendum notice
137	CY7C1484BV25-250AXI	Part affected by Addendum notice
138	CY7C53120E4-40AXI	Part affected by Addendum notice
139	CY7C68013A-56PVXC	Part affected by Addendum notice
140	CY7C68013A-56PVXCT	Part affected by Addendum notice
141	CY7C68013A-56PVXI	Part affected by Addendum notice
142	CY7C68014A-56PVXC	Part affected by Addendum notice
143	CY7C68300C-56PVXC	Part affected by Addendum notice
144	CY7C68300C-56PVXCT	Part affected by Addendum notice
145	CY8C24223A-24SXI	Part affected by Addendum notice
146	CY8C24223A-24SXIT	Part affected by Addendum notice
147	CY8C27243-24SXI	Part affected by Addendum notice
148	CY8C27243-24SXIT	Part affected by Addendum notice
149	CY8C27643-24PVXI	Part affected by Addendum notice
150	CY8C27643-24PVXIT	Part affected by Addendum notice
151	CY8C29466-24SXI	Part affected by Addendum notice
152	CY8C29466-24SXIT	Part affected by Addendum notice
153	CY8C29666-24PVXI	Part affected by Addendum notice
154	CY8C29666-24PVXIT	Part affected by Addendum notice
155	CY8C9540A-24PVXI	Part affected by Addendum notice
156	CY8C9540A-24PVXIT	Part affected by Addendum notice
157	CG7668AA	Part affected by Addendum notice
158	CG7668AAT	Part affected by Addendum notice

159	CG7690AA	Part affected by Addendum notice
160	CG7690AAT	Part affected by Addendum notice
161	CG7707AA	Part affected by Addendum notice
162	CG7713AA	Part affected by Addendum notice
163	CG7713AAT	Part affected by Addendum notice
164	CG7772AA	Part affected by Addendum notice
165	CG7794AA	Part affected by Addendum notice
166	CG7794AAT	Part affected by Addendum notice
167	CG7796AA	Part affected by Addendum notice
168	CG7796AAT	Part affected by Addendum notice
169	CG7797AA	Part affected by Addendum notice
170	CG7797AAT	Part affected by Addendum notice
171	CG7798AA	Part affected by Addendum notice
172	CG7798AAT	Part affected by Addendum notice
173	CG7802AA	Part affected by Addendum notice
174	CG7802AAT	Part affected by Addendum notice
175	CG7818AA	Part affected by Addendum notice
176	CG7818AAT	Part affected by Addendum notice
177	CG7820AA	Part affected by Addendum notice
178	CG7820AAT	Part affected by Addendum notice
179	CG7821AA	Part affected by Addendum notice
180	CG7821AAT	Part affected by Addendum notice
181	CG7866AA	Part affected by Addendum notice
182	CG7866AAT	Part affected by Addendum notice
183	CG7892AA	Part affected by Addendum notice
184	CG7892AAT	Part affected by Addendum notice
185	CG7901AA	Part affected by Addendum notice
186	CG7901AAT	Part affected by Addendum notice
187	CG7902AA	Part affected by Addendum notice
188	CG7902AAT	Part affected by Addendum notice
189	CG7910AA	Part affected by Addendum notice
190	CG7910AAT	Part affected by Addendum notice
191	CG7937AA	Part affected by Addendum notice
192	CG7945AA	Part affected by Addendum notice
193	CG7945AAT	Part affected by Addendum notice
194	CG7947AA	Part affected by Addendum notice
195	CG7947AAT	Part affected by Addendum notice
196	CG7952AA	Part affected by Addendum notice
197	CG7952AAT	Part affected by Addendum notice
198	CG7953AA	Part affected by Addendum notice
199	CG7953AAT	Part affected by Addendum notice
200	CG7965AA	Part affected by Addendum notice
201	CG7965AAT	Part affected by Addendum notice
202	CG7985AA	Part affected by Addendum notice
203	CG7985AAT	Part affected by Addendum notice
204	CG8014AA	Part affected by Addendum notice
205	CG8014AAT	Part affected by Addendum notice
206	CG8065AA	Part affected by Addendum notice
207	CG8065AAT	Part affected by Addendum notice
208	CP5788EM	Part affected by Addendum notice
209	CP5813CT	Part affected by Addendum notice
210	CP7896AT	Part affected by Addendum notice
211	CP7896ATT	Part affected by Addendum notice

212	CP7908AT	Part affected by Addendum notice
213	CP7908ATT	Part affected by Addendum notice
214	CP7909AT	Part affected by Addendum notice
215	CP7909ATT	Part affected by Addendum notice
216	CP7935AT	Part affected by Addendum notice
217	CP7935ATT	Part affected by Addendum notice
218	CP7936AT	Part affected by Addendum notice
219	CP7936ATT	Part affected by Addendum notice
220	CS7195AT	Part affected by Addendum notice
221	CS7195ATT	Part affected by Addendum notice
222	CY14B101KA-SP25XI	Part affected by PIN135258
223	CY14B101KA-SP25XIT	Part affected by PIN135258
224	CY14B101KA-SP45XI	Part affected by PIN135258
225	CY14B101KA-SP45XIT	Part affected by PIN135258
226	CY14B101KA-ZS25XI	Part affected by PIN135258
227	CY14B101KA-ZS25XIT	Part affected by PIN135258
228	CY14B101KA-ZS45XI	Part affected by PIN135258
229	CY14B101KA-ZS45XIT	Part affected by PIN135258
230	CY14B101LA-SP25XI	Part affected by PIN135258
231	CY14B101LA-SP25XIT	Part affected by PIN135258
232	CY14B101LA-SP25XIT	Part affected by PIN135258
233	CY14B101LA-SP25XIT	Part affected by PIN135258
234	CY14B101LA-SP45XI	Part affected by PIN135258
235	CY14B101LA-SP45XI	Part affected by PIN135258
236	CY14B101LA-SP45XIT	Part affected by PIN135258
237	CY14B101LA-SP45XIT	Part affected by PIN135258
238	CY14B101LA-ZS20XI	Part affected by PIN135258
239	CY14B101LA-ZS20XI	Part affected by PIN135258
240	CY14B101LA-ZS20XIT	Part affected by PIN135258
241	CY14B101LA-ZS20XIT	Part affected by PIN135258
242	CY14B101LA-ZS25XI	Part affected by PIN135258
243	CY14B101LA-ZS25XI	Part affected by PIN135258
244	CY14B101LA-ZS25XIT	Part affected by PIN135258
245	CY14B101LA-ZS25XIT	Part affected by PIN135258
246	CY14B101LA-ZS45XI	Part affected by PIN135258
247	CY14B101LA-ZS45XI	Part affected by PIN135258
248	CY14B101LA-ZS45XIT	Part affected by PIN135258
249	CY14B101LA-ZS45XIT	Part affected by PIN135258
250	CY14B101NA-ZS25XI	Part affected by PIN135258
251	CY14B101NA-ZS25XIT	Part affected by PIN135258
252	CY14B101NA-ZS45XI	Part affected by PIN135258
253	CY14B101NA-ZS45XIT	Part affected by PIN135258
254	CY14B104K-ZS25XI	Part affected by PIN135258
255	CY14B104K-ZS25XIT	Part affected by PIN135258
256	CY14B104K-ZS45XI	Part affected by PIN135258
257	CY14B104K-ZS45XIT	Part affected by PIN135258
258	CY14B104LA-ZS20XI	Part affected by PIN135258
259	CY14B104LA-ZS20XIT	Part affected by PIN135258
260	CY14B104LA-ZS25XI	Part affected by PIN135258
261	CY14B104LA-ZS25XIT	Part affected by PIN135258
262	CY14B104LA-ZS45XI	Part affected by PIN135258
263	CY14B104LA-ZS45XIT	Part affected by PIN135258
264	CY14B104NA-ZS20XI	Part affected by PIN135258

265	CY14B104NA-ZS20XI	Part affected by PIN135258
266	CY14B104NA-ZS20XIT	Part affected by PIN135258
267	CY14B104NA-ZS20XIT	Part affected by PIN135258
268	CY14B104NA-ZS25XI	Part affected by PIN135258
269	CY14B104NA-ZS25XI	Part affected by PIN135258
270	CY14B104NA-ZS25XIT	Part affected by PIN135258
271	CY14B104NA-ZS25XIT	Part affected by PIN135258
272	CY14B104NA-ZS45XI	Part affected by PIN135258
273	CY14B104NA-ZS45XI	Part affected by PIN135258
274	CY14B104NA-ZS45XIT	Part affected by PIN135258
275	CY14B104NA-ZS45XIT	Part affected by PIN135258
276	CY14B108K-ZS25XI	Part affected by PIN135258
277	CY14B108K-ZS25XIT	Part affected by PIN135258
278	CY14B108K-ZS45XI	Part affected by PIN135258
279	CY14B108K-ZS45XIT	Part affected by PIN135258
280	CY14B108L-ZS20XI	Part affected by PIN135258
281	CY14B108L-ZS20XIT	Part affected by PIN135258
282	CY14B108L-ZS25XI	Part affected by PIN135258
283	CY14B108L-ZS25XIT	Part affected by PIN135258
284	CY14B108L-ZS45XI	Part affected by PIN135258
285	CY14B108L-ZS45XIT	Part affected by PIN135258
286	CY14B256KA-SP25XI	Part affected by PIN135258
287	CY14B256KA-SP25XIT	Part affected by PIN135258
288	CY14B256KA-SP45XI	Part affected by PIN135258
289	CY14B256KA-SP45XIT	Part affected by PIN135258
290	CY14B256LA-SP25XI	Part affected by PIN135258
291	CY14B256LA-SP25XI	Part affected by PIN135258
292	CY14B256LA-SP25XIT	Part affected by PIN135258
293	CY14B256LA-SP25XIT	Part affected by PIN135258
294	CY14B256LA-SP45XI	Part affected by PIN135258
295	CY14B256LA-SP45XI	Part affected by PIN135258
296	CY14B256LA-SP45XIT	Part affected by PIN135258
297	CY14B256LA-SP45XIT	Part affected by PIN135258
298	CY14B256LA-ZS25XI	Part affected by PIN135258
299	CY14B256LA-ZS25XI	Part affected by PIN135258
300	CY14B256LA-ZS25XIT	Part affected by PIN135258
301	CY14B256LA-ZS25XIT	Part affected by PIN135258
302	CY62128BNLL-55SXI	Part affected by PIN135258
303	CY62128BNLL-55SXIT	Part affected by PIN135258
304	CY62128ELL-45SXI	Part affected by PIN135258
305	CY62128ELL-45SXI	Part affected by PIN135258
306	CY62128ELL-45SXIT	Part affected by PIN135258
307	CY62128ELL-45SXIT	Part affected by PIN135258
308	CY62128ELL-45ZAXI	Part affected by PIN135258
309	CY62128ELL-45ZAXIT	Part affected by PIN135258
310	CY62128EV30LL-45SXI	Part affected by PIN135258
311	CY62128EV30LL-45SXI	Part affected by PIN135258
312	CY62128EV30LL-45SXIT	Part affected by PIN135258
313	CY62128EV30LL-45SXIT	Part affected by PIN135258
314	CY62128EV30LL-45ZAXI	Part affected by PIN135258
315	CY62128EV30LL-45ZAXIT	Part affected by PIN135258
316	CY62136ESL-45ZSXI	Part affected by PIN135258
317	CY62136ESL-45ZSXIT	Part affected by PIN135258

318	CY62136EV30LL-45ZSXI	Part affected by PIN135258
319	CY62136EV30LL-45ZSXIT	Part affected by PIN135258
320	CY62136FV30LL-45ZSXI	Part affected by PIN135258
321	CY62136FV30LL-45ZSXIT	Part affected by PIN135258
322	CY62137EV30LL-45ZSXI	Part affected by PIN135258
323	CY62137EV30LL-45ZSXIT	Part affected by PIN135258
324	CY62137FV30LL-45ZSXI	Part affected by PIN135258
325	CY62137FV30LL-45ZSXI	Part affected by PIN135258
326	CY62138FLL-45SXI	Part affected by PIN135258
327	CY62138FLL-45SXIT	Part affected by PIN135258
328	CY62138FV30LL-45SXI	Part affected by PIN135258
329	CY62138FV30LL-45SXIT	Part affected by PIN135258
330	CY62138FV30LL-45ZAXI	Part affected by PIN135258
331	CY62138FV30LL-45ZAXIT	Part affected by PIN135258
332	CY62146ELL-45ZSXI	Part affected by PIN135258
333	CY62146ELL-45ZSXIT	Part affected by PIN135258
334	CY62146ESL-45ZSXI	Part affected by PIN135258
335	CY62146ESL-45ZSXIT	Part affected by PIN135258
336	CY62146EV30LL-45ZSXI	Part affected by PIN135258
337	CY62146EV30LL-45ZSXIT	Part affected by PIN135258
338	CY621472E30LL-45ZSXI	Part affected by PIN135258
339	CY621472E30LL-45ZSXIT	Part affected by PIN135258
340	CY621472EV30LL-45ZSXI	Part affected by PIN135258
341	CY62147EV30LL-45ZSXI	Part affected by PIN135258
342	CY62147EV30LL-45ZSXIT	Part affected by PIN135258
343	CY62148BNLL-70SXI	Part affected by PIN135258
344	CY62148BNLL-70SXI	Part affected by PIN135258
345	CY62148DV30LL-55SXI	Part affected by PIN135258
346	CY62148DV30LL-55SXIT	Part affected by PIN135258
347	CY62148ELL-55SXI	Part affected by PIN135258
348	CY62148ELL-55SXI	Part affected by PIN135258
349	CY62148ELL-55SXIT	Part affected by PIN135258
350	CY62148ELL-55SXIT	Part affected by PIN135258
351	CY62148EV30LL-55SXI	Part affected by PIN135258
352	CY62148EV30LL-55SXI	Part affected by PIN135258
353	CY62148EV30LL-55SXIT	Part affected by PIN135258
354	CY62148EV30LL-55SXIT	Part affected by PIN135258
355	CY62157ELL-45ZSXI	Part affected by PIN135258
356	CY62157ELL-45ZSXIT	Part affected by PIN135258
357	CY62157ESL-45ZSXI	Part affected by PIN135258
358	CY62157ESL-45ZSXIT	Part affected by PIN135258
359	CY62157EV30LL-45ZSXI	Part affected by PIN135258
360	CY62158ELL-45ZSXI	Part affected by PIN135258
361	CY62158ELL-45ZSXIT	Part affected by PIN135258
362	CY62158EV30LL-45ZSXI	Part affected by PIN135258
363	CY62158EV30LL-45ZSXIT	Part affected by PIN135258
364	CY62256EV18LL-70SNXI	Part affected by PIN135258
365	CY62256EV18LL-70SNXIT	Part affected by PIN135258
366	CY62256NLL-55SNXI	Part affected by PIN135258
367	CY62256NLL-55SNXI	Part affected by PIN135258
368	CY62256NLL-55SNXI	Part affected by PIN135258
369	CY62256NLL-55SNXI	Part affected by PIN135258
370	CY62256NLL-55SNXIT	Part affected by PIN135258

371	CY62256NLL-55SNXIT	Part affected by PIN135258
372	CY62256NLL-55SNXIT	Part affected by PIN135258
373	CY62256NLL-55SNXIT	Part affected by PIN135258
374	CY62256NLL-70SNXC	Part affected by PIN135258
375	CY62256NLL-70SNXC	Part affected by PIN135258
376	CY62256NLL-70SNXC	Part affected by PIN135258
377	CY62256NLL-70SNXCT	Part affected by PIN135258
378	CY62256NLL-70SNXCT	Part affected by PIN135258
379	CY62256NLL-70SNXCT	Part affected by PIN135258
380	CY62256VNLL-70SNXI	Part affected by PIN135258
381	CY62256VNLL-70SNXI	Part affected by PIN135258
382	CY62256VNLL-70SNXIT	Part affected by PIN135258
383	CY62256VNLL-70SNXIT	Part affected by PIN135258
384	CY6264-55SNXI	Part affected by PIN135258
385	CY6264-55SNXIT	Part affected by PIN135258
386	CY6264-70SNXC	Part affected by PIN135258
387	CY6264-70SNXCT	Part affected by PIN135258
388	CY7C1009D-10VXI	Part affected by PIN135258
389	CY7C1009D-10VXIT	Part affected by PIN135258
390	CY7C1011DV33-10ZSXI	Part affected by PIN135258
391	CY7C1011DV33-10ZSXIT	Part affected by PIN135258
392	CY7C1018DV33-10VXI	Part affected by PIN135258
393	CY7C1018DV33-10VXI	Part affected by PIN135258
394	CY7C1019D-10VXI	Part affected by PIN135258
395	CY7C1019D-10VXIT	Part affected by PIN135258
396	CY7C1019DV33-10VXI	Part affected by PIN135258
397	CY7C1019DV33-10VXIT	Part affected by PIN135258
398	CY7C1020D-10VXI	Part affected by PIN135258
399	CY7C1020D-10VXIT	Part affected by PIN135258
400	CY7C1020D-10ZSXI	Part affected by PIN135258
401	CY7C1020D-10ZSXIT	Part affected by PIN135258
402	CY7C1020DV33-10ZSXI	Part affected by PIN135258
403	CY7C1020DV33-10ZSXIT	Part affected by PIN135258
404	CY7C1021CV33-10ZXC	Part affected by PIN135258
405	CY7C1021CV33-10ZXCT	Part affected by PIN135258
406	CY7C1021CV33-10ZXI	Part affected by PIN135258
407	CY7C1021D-10VXI	Part affected by PIN135258
408	CY7C1021D-10VXIT	Part affected by PIN135258
409	CY7C1021D-10ZSXI	Part affected by PIN135258
410	CY7C1021D-10ZSXIT	Part affected by PIN135258
411	CY7C1021DV33-10VXI	Part affected by PIN135258
412	CY7C1021DV33-10VXIT	Part affected by PIN135258
413	CY7C1021DV33-10ZSXI	Part affected by PIN135258
414	CY7C1021DV33-10ZSXIT	Part affected by PIN135258
415	CY7C1041CV33-10ZXC	Part affected by PIN135258
416	CY7C1041CV33-10ZXCT	Part affected by PIN135258
417	CY7C1041CV33-10ZXI	Part affected by PIN135258
418	CY7C1041D-10VXI	Part affected by PIN135258
419	CY7C1041D-10VXIT	Part affected by PIN135258
420	CY7C1041D-10ZSXI	Part affected by PIN135258
421	CY7C1041D-10ZSXIT	Part affected by PIN135258
422	CY7C1041DV33-10VXI	Part affected by PIN135258
423	CY7C1041DV33-10VXIT	Part affected by PIN135258

424	CY7C1041DV33-10ZSXI	Part affected by PIN135258
425	CY7C1041DV33-10ZSXIT	Part affected by PIN135258
426	CY7C1049CV33-8ZSXC	Part affected by PIN135258
427	CY7C1049DV33-10ZSXI	Part affected by PIN135258
428	CY7C1049DV33-10ZSXIT	Part affected by PIN135258
429	CY7C109D-10VXI	Part affected by PIN135258
430	CY7C109D-10VXIT	Part affected by PIN135258
431	CY7C1325S-100AXC	Part affected by PIN135258
432	CY7C1325S-100AXCT	Part affected by PIN135258
433	CY7C1327G-133AXI	Part affected by PIN135258
434	CY7C1327G-133AXIT	Part affected by PIN135258
435	CY7C1327G-166AXC	Part affected by PIN135258
436	CY7C1327G-166AXCT	Part affected by PIN135258
437	CY7C1327S-166AXC	Part affected by PIN135258
438	CY7C1328G-133AXI	Part affected by PIN135258
439	CY7C1328G-133AXIT	Part affected by PIN135258
440	CY7C1338S-100AXC	Part affected by PIN135258
441	CY7C1338S-100AXCT	Part affected by PIN135258
442	CY7C1339G-133AXC	Part affected by PIN135258
443	CY7C1339G-133AXCT	Part affected by PIN135258
444	CY7C1339S-133AXC	Part affected by PIN135258
445	CY7C1345G-100AXC	Part affected by PIN135258
446	CY7C1345G-100AXCT	Part affected by PIN135258
447	CY7C1345G-100AXI	Part affected by PIN135258
448	CY7C1345G-100AXIT	Part affected by PIN135258
449	CY7C1345S-100AXC	Part affected by PIN135258
450	CY7C1345S-100AXCT	Part affected by PIN135258
451	CY7C1347G-133AXC	Part affected by PIN135258
452	CY7C1347G-133AXCT	Part affected by PIN135258
453	CY7C1347G-166AXC	Part affected by PIN135258
454	CY7C1347G-166AXCT	Part affected by PIN135258
455	CY7C1347G-200AXC	Part affected by PIN135258
456	CY7C1347G-200AXCT	Part affected by PIN135258
457	CY7C1347G-250AXC	Part affected by PIN135258
458	CY7C1347S-133AXC	Part affected by PIN135258
459	CY7C1347S-133AXCT	Part affected by PIN135258
460	CY7C1350G-200AXC	Part affected by PIN135258
461	CY7C1350G-200AXCT	Part affected by PIN135258
462	CY7C1350G-200AXI	Part affected by PIN135258
463	CY7C1350S-133AXC	Part affected by PIN135258
464	CY7C1350S-133AXCT	Part affected by PIN135258
465	CY7C1350S-133AXI	Part affected by PIN135258
466	CY7C1354C-166AXC	Part affected by PIN135258
467	CY7C1354C-166AXCT	Part affected by PIN135258
468	CY7C1354C-166AXI	Part affected by PIN135258
469	CY7C1354C-166AXIT	Part affected by PIN135258
470	CY7C1354C-200AXC	Part affected by PIN135258
471	CY7C1354C-200AXCT	Part affected by PIN135258
472	CY7C1354C-200AXI	Part affected by PIN135258
473	CY7C1354C-200AXIT	Part affected by PIN135258
474	CY7C1354SV25-166AXC	Part affected by PIN135258
475	CY7C1354SV25-166AXCT	Part affected by PIN135258
476	CY7C1355C-133AXC	Part affected by PIN135258

477	CY7C1355C-133AXCT	Part affected by PIN135258
478	CY7C1356C-166AXC	Part affected by PIN135258
479	CY7C1356C-166AXCT	Part affected by PIN135258
480	CY7C1356C-166AXI	Part affected by PIN135258
481	CY7C1356C-166AXIT	Part affected by PIN135258
482	CY7C1356C-250AXC	Part affected by PIN135258
483	CY7C1356C-250AXCT	Part affected by PIN135258
484	CY7C1356CV25-166AXC	Part affected by PIN135258
485	CY7C1356CV25-166AXCT	Part affected by PIN135258
486	CY7C1356SV25-166AXC	Part affected by PIN135258
487	CY7C1356SV25-166AXCT	Part affected by PIN135258
488	CY7C1356SV25-200AXC	Part affected by PIN135258
489	CY7C1357C-133AXC	Part affected by PIN135258
490	CY7C1357C-133AXCT	Part affected by PIN135258
491	CY7C1357S-100AXC	Part affected by PIN135258
492	CY7C1357S-100AXCT	Part affected by PIN135258
493	CY7C1360S-166AXC	Part affected by PIN135258
494	CY7C1360S-166AXCT	Part affected by PIN135258
495	CY7C1361C-100AXC	Part affected by PIN135258
496	CY7C1361C-100AXCT	Part affected by PIN135258
497	CY7C1361C-133AJXC	Part affected by PIN135258
498	CY7C1361C-133AJXCT	Part affected by PIN135258
499	CY7C1361C-133AXC	Part affected by PIN135258
500	CY7C1361C-133AXCT	Part affected by PIN135258
501	CY7C1361C-133AXI	Part affected by PIN135258
502	CY7C1361C-133AXIT	Part affected by PIN135258
503	CY7C1362C-166AJXC	Part affected by PIN135258
504	CY7C1363C-133AJXC	Part affected by PIN135258
505	CY7C1363C-133AJXI	Part affected by PIN135258
506	CY7C1363C-133AXC	Part affected by PIN135258
507	CY7C1363C-133AXCT	Part affected by PIN135258
508	CY7C1366C-166AXC	Part affected by PIN135258
509	CY7C1366C-166AXCT	Part affected by PIN135258
510	CY7C1367C-166AXC	Part affected by PIN135258
511	CY7C1367C-166AXCT	Part affected by PIN135258
512	CY7C1370D-167AXC	Part affected by PIN135258
513	CY7C1370D-167AXCT	Part affected by PIN135258
514	CY7C1370D-167AXI	Part affected by PIN135258
515	CY7C1370D-167AXIT	Part affected by PIN135258
516	CY7C1370D-200AXC	Part affected by PIN135258
517	CY7C1370D-200AXCT	Part affected by PIN135258
518	CY7C1370D-200AXI	Part affected by PIN135258
519	CY7C1370D-250AXC	Part affected by PIN135258
520	CY7C1370D-250AXCT	Part affected by PIN135258
521	CY7C1370D-250AXI	Part affected by PIN135258
522	CY7C1370DV25-167AXC	Part affected by PIN135258
523	CY7C1370DV25-167AXCT	Part affected by PIN135258
524	CY7C1370DV25-200AXC	Part affected by PIN135258
525	CY7C1370DV25-200AXCT	Part affected by PIN135258
526	CY7C1370S-167AXC	Part affected by PIN135258
527	CY7C1370S-200AXC	Part affected by PIN135258
528	CY7C1370S-200AXCT	Part affected by PIN135258
529	CY7C1370SV25-167AXC	Part affected by PIN135258

530	CY7C1370SV25-167AXCT	Part affected by PIN135258
531	CY7C1370SV25-200AXC	Part affected by PIN135258
532	CY7C1371D-100AXC	Part affected by PIN135258
533	CY7C1371D-100AXCT	Part affected by PIN135258
534	CY7C1371D-100AXI	Part affected by PIN135258
535	CY7C1371D-133AXC	Part affected by PIN135258
536	CY7C1371D-133AXCT	Part affected by PIN135258
537	CY7C1371DV33-133AXI	Part affected by PIN135258
538	CY7C1371S-133AXC	Part affected by PIN135258
539	CY7C1371S-133AXCT	Part affected by PIN135258
540	CY7C1372D-167AXC	Part affected by PIN135258
541	CY7C1372D-167AXCT	Part affected by PIN135258
542	CY7C1372D-167AXI	Part affected by PIN135258
543	CY7C1372D-167AXIT	Part affected by PIN135258
544	CY7C1372D-200AXC	Part affected by PIN135258
545	CY7C1372DV25-167AXC	Part affected by PIN135258
546	CY7C1372DV25-167AXCT	Part affected by PIN135258
547	CY7C1372S-167AXC	Part affected by PIN135258
548	CY7C1372SV25-167AXC	Part affected by PIN135258
549	CY7C1372SV25-167AXCT	Part affected by PIN135258
550	CY7C1373D-100AXC	Part affected by PIN135258
551	CY7C1373D-133AXI	Part affected by PIN135258
552	CY7C1380D-167AXC	Part affected by PIN135258
553	CY7C1380D-167AXCT	Part affected by PIN135258
554	CY7C1380D-167AXI	Part affected by PIN135258
555	CY7C1380D-167AXIT	Part affected by PIN135258
556	CY7C1380D-200AXC	Part affected by PIN135258
557	CY7C1380D-250AXC	Part affected by PIN135258
558	CY7C1380DV33-200AXI	Part affected by PIN135258
559	CY7C1380S-167AXC	Part affected by PIN135258
560	CY7C1380S-167AXCT	Part affected by PIN135258
561	CY7C1381D-100AXC	Part affected by PIN135258
562	CY7C1381D-100AXCT	Part affected by PIN135258
563	CY7C1381D-133AXC	Part affected by PIN135258
564	CY7C1381D-133AXCT	Part affected by PIN135258
565	CY7C1381D-133AXI	Part affected by PIN135258
566	CY7C1381D-133AXIT	Part affected by PIN135258
567	CY7C1381S-133AXC	Part affected by PIN135258
568	CY7C1382D-167AXC	Part affected by PIN135258
569	CY7C1382D-200AXC	Part affected by PIN135258
570	CY7C1383D-133AXC	Part affected by PIN135258
571	CY7C1383D-133AXCT	Part affected by PIN135258
572	CY7C1383D-133AXI	Part affected by PIN135258
573	CY7C1386D-167AXC	Part affected by PIN135258
574	CY7C1386D-167AXCT	Part affected by PIN135258
575	CY7C1386D-200AXC	Part affected by PIN135258
576	CY7C1386D-200AXCT	Part affected by PIN135258
577	CY7C1386S-167AXC	Part affected by PIN135258
578	CY7C1387D-167AXC	Part affected by PIN135258
579	CY7C1387D-167AXCT	Part affected by PIN135258
580	CY7C53120E2-10SXI	Part affected by PIN135258
581	CY7C53120E2-10SXI	Part affected by PIN135258
582	CY7C53120E4-40SXI	Part affected by PIN135258

583	CY7C53120E4-40SXI	Part affected by PIN135258
584	CY7C53120E4-40SXIT	Part affected by PIN135258
585	CY7C53120E4-40SXIT	Part affected by PIN135258
586	CY7C53150-20AXI	Part affected by PIN135258
587	CY7C53150-20AXI	Part affected by PIN135258
588	CY7C53150-20AXI	Part affected by PIN135258
589	CY7C53150-20AXIT	Part affected by PIN135258
590	CY7C53150-20AXIT	Part affected by PIN135258
591	CY7C53150-20AXIT	Part affected by PIN135258
592	CY7C64713-100AXC	Part affected by PIN135258
593	CY7C64713-128AXC	Part affected by PIN135258
594	CY7C64713-128AXC	Part affected by PIN135258
595	CY7C68013A-100AXC	Part affected by PIN135258
596	CY7C68013A-100AXI	Part affected by PIN135258
597	CY7C68013A-128AXC	Part affected by PIN135258
598	CY7C68013A-128AXC	Part affected by PIN135258
599	CY7C68013A-128AXI	Part affected by PIN135258
600	CY7C68013A-128AXI	Part affected by PIN135258
601	CY7C68014A-100AXC	Part affected by PIN135258
602	CY7C68014A-128AXC	Part affected by PIN135258
603	CY7C68014A-128AXC	Part affected by PIN135258
604	CY7C68320C-100AXC	Part affected by PIN135258
605	CY7C68320C-100AXC	Part affected by PIN135258
606	CY8C20536A-24PVXI	Part affected by PIN135258
607	CY8C20536A-24PVXI	Part affected by PIN135258
608	CY8C20536A-24PVXIT	Part affected by PIN135258
609	CY8C20536A-24PVXIT	Part affected by PIN135258
610	CY8C20546A-24PVXI	Part affected by PIN135258
611	CY8C20546A-24PVXI	Part affected by PIN135258
612	CY8C20546A-24PVXIT	Part affected by PIN135258
613	CY8C20546A-24PVXIT	Part affected by PIN135258
614	CY8C20566A-24PVXI	Part affected by PIN135258
615	CY8C20566A-24PVXI	Part affected by PIN135258
616	CY8C20566A-24PVXIT	Part affected by PIN135258
617	CY8C20566A-24PVXIT	Part affected by PIN135258
618	CY8C21345-24SXI	Part affected by PIN135258
619	CY8C21345-24SXIT	Part affected by PIN135258
620	CY8C22345-24SXI	Part affected by PIN135258
621	CY8C22345-24SXIT	Part affected by PIN135258
622	CY8C24423A-24SXI	Part affected by PIN135258
623	CY8C24423A-24SXI	Part affected by PIN135258
624	CY8C24423A-24SXIT	Part affected by PIN135258
625	CY8C24423A-24SXIT	Part affected by PIN135258
626	CY8C27443-24SXI	Part affected by PIN135258
627	CY8C27443-24SXI	Part affected by PIN135258
628	CY8C27443-24SXI	Part affected by PIN135258
629	CY8C27443-24SXIT	Part affected by PIN135258
630	CY8C27443-24SXIT	Part affected by PIN135258
631	CY8C27443-24SXIT	Part affected by PIN135258
632	CY8C27543-24AXI	Part affected by PIN135258
633	CY8C27543-24AXI	Part affected by PIN135258
634	CY8C27543-24AXI	Part affected by PIN135258
635	CY8C27543-24AXIT	Part affected by PIN135258

636	CY8C27543-24AXIT	Part affected by PIN135258
637	CY8C27543-24AXIT	Part affected by PIN135258
638	CY8C29566-24AXI	Part affected by PIN135258
639	CY8C29566-24AXI	Part affected by PIN135258
640	CY8C29566-24AXI	Part affected by PIN135258
641	CY8C29566-24AXIT	Part affected by PIN135258
642	CY8C29566-24AXIT	Part affected by PIN135258
643	CY8C29566-24AXIT	Part affected by PIN135258
644	CY8C3244AXI-153	Part affected by PIN135258
645	CY8C3244AXI-153T	Part affected by PIN135258
646	CY8C3244PVI-133	Part affected by PIN135258
647	CY8C3244PVI-133T	Part affected by PIN135258
648	CY8C3245AXI-158	Part affected by PIN135258
649	CY8C3245AXI-158T	Part affected by PIN135258
650	CY8C3245AXI-166	Part affected by PIN135258
651	CY8C3245AXI-166T	Part affected by PIN135258
652	CY8C3245PVI-134	Part affected by PIN135258
653	CY8C3245PVI-134T	Part affected by PIN135258
654	CY8C3245PVI-150	Part affected by PIN135258
655	CY8C3245PVI-150T	Part affected by PIN135258
656	CY8C3246AXI-131	Part affected by PIN135258
657	CY8C3246AXI-131T	Part affected by PIN135258
658	CY8C3246AXI-138	Part affected by PIN135258
659	CY8C3246AXI-138T	Part affected by PIN135258
660	CY8C3246PVI-122	Part affected by PIN135258
661	CY8C3246PVI-122T	Part affected by PIN135258
662	CY8C3246PVI-147	Part affected by PIN135258
663	CY8C3246PVI-147T	Part affected by PIN135258
664	CY8C3444PVI-100	Part affected by PIN135258
665	CY8C3444PVI-100T	Part affected by PIN135258
666	CY8C3445AXI-104	Part affected by PIN135258
667	CY8C3445AXI-104T	Part affected by PIN135258
668	CY8C3445AXI-108	Part affected by PIN135258
669	CY8C3445AXI-108T	Part affected by PIN135258
670	CY8C3445PVI-090	Part affected by PIN135258
671	CY8C3445PVI-090T	Part affected by PIN135258
672	CY8C3445PVI-094	Part affected by PIN135258
673	CY8C3445PVI-094T	Part affected by PIN135258
674	CY8C3446AXI-099	Part affected by PIN135258
675	CY8C3446AXI-099T	Part affected by PIN135258
676	CY8C3446AXI-105	Part affected by PIN135258
677	CY8C3446AXI-105T	Part affected by PIN135258
678	CY8C3446PVI-076	Part affected by PIN135258
679	CY8C3446PVI-076T	Part affected by PIN135258
680	CY8C3446PVI-102	Part affected by PIN135258
681	CY8C3446PVI-102T	Part affected by PIN135258
682	CY8C3665AXI-198	Part affected by PIN135258
683	CY8C3665AXI-198T	Part affected by PIN135258
684	CY8C3665PVI-008	Part affected by PIN135258
685	CY8C3665PVI-008T	Part affected by PIN135258
686	CY8C3666AXI-036	Part affected by PIN135258
687	CY8C3666AXI-036T	Part affected by PIN135258
688	CY8C3666AXI-037	Part affected by PIN135258

689	CY8C3666AXI-037T	Part affected by PIN135258
690	CY8C3666AXI-052	Part affected by PIN135258
691	CY8C3666AXI-052T	Part affected by PIN135258
692	CY8C3666AXI-200	Part affected by PIN135258
693	CY8C3666AXI-200T	Part affected by PIN135258
694	CY8C3666AXI-202	Part affected by PIN135258
695	CY8C3666AXI-202T	Part affected by PIN135258
696	CY8C3865AXI-019	Part affected by PIN135258
697	CY8C3865AXI-019T	Part affected by PIN135258
698	CY8C3865AXI-204	Part affected by PIN135258
699	CY8C3865AXI-204T	Part affected by PIN135258
700	CY8C3866AXI-035	Part affected by PIN135258
701	CY8C3866AXI-035T	Part affected by PIN135258
702	CY8C3866AXI-039	Part affected by PIN135258
703	CY8C3866AXI-039T	Part affected by PIN135258
704	CY8C3866AXI-040	Part affected by PIN135258
705	CY8C3866AXI-040T	Part affected by PIN135258
706	CY8C3866AXI-206	Part affected by PIN135258
707	CY8C3866AXI-206T	Part affected by PIN135258
708	CY8C3866AXI-208	Part affected by PIN135258
709	CY8C3866AXI-208T	Part affected by PIN135258
710	CY8C3866PVI-021	Part affected by PIN135258
711	CY8C3866PVI-021T	Part affected by PIN135258
712	CY8C3866PVI-070	Part affected by PIN135258
713	CY8C3866PVI-070T	Part affected by PIN135258
714	CY8CTMA884AI-13	Part affected by PIN135258
715	CYATB108LD-ZS45XI	Part affected by PIN135258
716	CG6707AM	Part affected by PIN135258
717	CG6707AM	Part affected by PIN135258
718	CG6707AMT	Part affected by PIN135258
719	CG6707AMT	Part affected by PIN135258
720	CG6713AM	Part affected by PIN135258
721	CG6713AM	Part affected by PIN135258
722	CG6713AMT	Part affected by PIN135258
723	CG6713AMT	Part affected by PIN135258
724	CG6715AM	Part affected by PIN135258
725	CG6715AM	Part affected by PIN135258
726	CG6715AM	Part affected by PIN135258
727	CG6715AM	Part affected by PIN135258
728	CG6715AMT	Part affected by PIN135258
729	CG6715AMT	Part affected by PIN135258
730	CG6715AMT	Part affected by PIN135258
731	CG6715AMT	Part affected by PIN135258
732	CG6719AM	Part affected by PIN135258
733	CG6719AMT	Part affected by PIN135258
734	CG6720AM	Part affected by PIN135258
735	CG6720AMT	Part affected by PIN135258
736	CG6722AM	Part affected by PIN135258
737	CG6722AMT	Part affected by PIN135258
738	CG6727AM	Part affected by PIN135258
739	CG6727AM	Part affected by PIN135258
740	CG6727AMT	Part affected by PIN135258
741	CG6727AMT	Part affected by PIN135258

742	CG6740AT	Part affected by PIN135258
743	CG6740AT	Part affected by PIN135258
744	CG6740ATT	Part affected by PIN135258
745	CG6740ATT	Part affected by PIN135258
746	CG6821AM	Part affected by PIN135258
747	CG6821AMT	Part affected by PIN135258
748	CG6834AM	Part affected by PIN135258
749	CG6834AMT	Part affected by PIN135258
750	CG7035AM	Part affected by PIN135258
751	CG7035AMT	Part affected by PIN135258
752	CG7036AM	Part affected by PIN135258
753	CG7036AMT	Part affected by PIN135258
754	CG7099AM	Part affected by PIN135258
755	CG7099AMT	Part affected by PIN135258
756	CG7109AM	Part affected by PIN135258
757	CG7109AMT	Part affected by PIN135258
758	CG7117AM	Part affected by PIN135258
759	CG7117AMT	Part affected by PIN135258
760	CG7285AT	Part affected by PIN135258
761	CG7285AT	Part affected by PIN135258
762	CG7299AT	Part affected by PIN135258
763	CG7299ATT	Part affected by PIN135258
764	CG7328AM	Part affected by PIN135258
765	CG7328AMT	Part affected by PIN135258
766	CG7434AM	Part affected by PIN135258
767	CG7512AM	Part affected by PIN135258
768	CG7512AMT	Part affected by PIN135258
769	CG7516AA	Part affected by PIN135258
770	CG7516AAT	Part affected by PIN135258
771	CG7604AT	Part affected by PIN135258
772	CG7604ATT	Part affected by PIN135258
773	CG7647AA	Part affected by PIN135258
774	CG7647AAT	Part affected by PIN135258
775	CG7659AA	Part affected by PIN135258
776	CG7659AA	Part affected by PIN135258
777	CG7661AA	Part affected by PIN135258
778	CG7661AA	Part affected by PIN135258
779	CG7661AA	Part affected by PIN135258
780	CG7661AAT	Part affected by PIN135258
781	CG7661AAT	Part affected by PIN135258
782	CG7661AAT	Part affected by PIN135258
783	CG7671AA	Part affected by PIN135258
784	CG7671AAT	Part affected by PIN135258
785	CG7672AA	Part affected by PIN135258
786	CG7672AA	Part affected by PIN135258
787	CG7672AAT	Part affected by PIN135258
788	CG7672AAT	Part affected by PIN135258
789	CG7679AA	Part affected by PIN135258
790	CG7679AAT	Part affected by PIN135258
791	CG7684AA	Part affected by PIN135258
792	CG7684AAT	Part affected by PIN135258
793	CG7685AA	Part affected by PIN135258
794	CG7686AA	Part affected by PIN135258

795	CG7686AA	Part affected by PIN135258
796	CG7686AA	Part affected by PIN135258
797	CG7686AAT	Part affected by PIN135258
798	CG7686AAT	Part affected by PIN135258
799	CG7686AAT	Part affected by PIN135258
800	CG7689AA	Part affected by PIN135258
801	CG7689AAT	Part affected by PIN135258
802	CG7691AA	Part affected by PIN135258
803	CG7691AAT	Part affected by PIN135258
804	CG7695AA	Part affected by PIN135258
805	CG7695AAT	Part affected by PIN135258
806	CG7714AA	Part affected by PIN135258
807	CG7714AAT	Part affected by PIN135258
808	CG7716AA	Part affected by PIN135258
809	CG7716AA	Part affected by PIN135258
810	CG7721AA	Part affected by PIN135258
811	CG7721AAT	Part affected by PIN135258
812	CG7740AA	Part affected by PIN135258
813	CG7740AAT	Part affected by PIN135258
814	CG7751AA	Part affected by PIN135258
815	CG7751AAT	Part affected by PIN135258
816	CG7755AA	Part affected by PIN135258
817	CG7755AAT	Part affected by PIN135258
818	CG7803AA	Part affected by PIN135258
819	CG7803AAT	Part affected by PIN135258
820	CG7810AA	Part affected by PIN135258
821	CG7810AAT	Part affected by PIN135258
822	CG7832AA	Part affected by PIN135258
823	CG7832AAT	Part affected by PIN135258
824	CG7833AA	Part affected by PIN135258
825	CG7833AAT	Part affected by PIN135258
826	CG7839AA	Part affected by PIN135258
827	CG7839AAT	Part affected by PIN135258
828	CG7840AA	Part affected by PIN135258
829	CG7840AAT	Part affected by PIN135258
830	CG7841AA	Part affected by PIN135258
831	CG7841AAT	Part affected by PIN135258
832	CG7859AA	Part affected by PIN135258
833	CG7859AAT	Part affected by PIN135258
834	CG7867AA	Part affected by PIN135258
835	CG7888AA	Part affected by PIN135258
836	CG7888AAT	Part affected by PIN135258
837	CG7916AA	Part affected by PIN135258
838	CG7916AAT	Part affected by PIN135258
839	CG7918AA	Part affected by PIN135258
840	CG7918AA	Part affected by PIN135258
841	CG7918AAT	Part affected by PIN135258
842	CG7918AAT	Part affected by PIN135258
843	CP5789EM	Part affected by PIN135258
844	CP5789EM	Part affected by PIN135258
845	CP5789EMT	Part affected by PIN135258
846	CP5789EMT	Part affected by PIN135258
847	CP5790DM	Part affected by PIN135258

848	CP5790DMT	Part affected by PIN135258
849	CP6332AM	Part affected by PIN135258
850	CP6332AM	Part affected by PIN135258
851	CP6332AM	Part affected by PIN135258
852	CP6332AMT	Part affected by PIN135258
853	CP6332AMT	Part affected by PIN135258
854	CP6332AMT	Part affected by PIN135258
855	CP7520AT	Part affected by PIN135258
856	CP7520AT	Part affected by PIN135258
857	CP7520ATT	Part affected by PIN135258
858	CP7520ATT	Part affected by PIN135258
859	CP7538AT	Part affected by PIN135258
860	CP7538ATT	Part affected by PIN135258
861	CP7627AT	Part affected by PIN135258
862	CP7627ATT	Part affected by PIN135258
863	CS6567AM	Part affected by PIN135258
864	CS6567AM	Part affected by PIN135258
865	CS6567AM	Part affected by PIN135258
866	CS6567AMT	Part affected by PIN135258
867	CS6567AMT	Part affected by PIN135258
868	CS6567AMT	Part affected by PIN135258
869	CS7568AT	Part affected by PIN135258
870	CS7568ATT	Part affected by PIN135258
871	CS7642AT	Part affected by PIN135258
872	CS7642ATT	Part affected by PIN135258
873	CS7655AM	Part affected by PIN135258
874	CS7655AMT	Part affected by PIN135258
875	CS7897AM	Part affected by PIN135258
876	CS7897AMT	Part affected by PIN135258