

### 1 Products affected

Product hierarchy no. *			archy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Туре				
01	002	012	0000000673	0031.2550	Circuit Protection		
				0031.2560		FUA	
				0031.2570			

## 2 Type of change

The inscription at the socket of the fuseholder changes. The voltage rating acc. to UL/CSA is new 600V.

# 3 Detailed description of change

The inscription changes as follows.



#### 4 Reason of change

The fuseholder FUA has a voltage rating acc. to UL 4248-1 / CSA C22.2 no 4248.1 of 600V (AC/DC). This rating is corrected on the inscription of the socket. Because of this, the layout of the inscription changes.

#### 5 Release date

The change will be rolled-out starting in November 2015, depending on the stock.

#### 6 Impact of change and recommended action

Form:	Yes (inscription only)
Fit:	No
Function:	No
Production Site:	No
Product Label:	No

#### 7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet	FUA	Web Link FUA

	0118.2213						
creation date	created by	release date	released by	notification no.	revision	page	
2014-05-23	dislercy	2014-07-01	dislercy	26340	_	1 of 1	