

## 1 Products affected

| Product hierarchy no. * |     |      | Part no.   | SBU            | Type / Description | Customer part no. |
|-------------------------|-----|------|------------|----------------|--------------------|-------------------|
| SBU / PG                | PGU | Type |            |                |                    |                   |
| 02                      | 007 | 013  | 0000002409 | See list below | Appliance outlet   | 5216              |

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)


| List of part numbers affected |           |           |  |  |  |  |  |
|-------------------------------|-----------|-----------|--|--|--|--|--|
| 6183.0002                     | 6183.0003 | 6183.0013 |  |  |  |  |  |

## 2 Type of change

Modification of rating mark

## 3 Detailed description of change

Change of rated current acc. to UL 60320



## 4 Reason of change

Rated current adjusted to UL 60320

## 5 Released date

The change will be rolled-out individually by all part numbers affected starting ww 08/2014 and last approx. 9 months.

## 6 Impact of change and recommended action

Form: New current rating according to UL 60320  
Fit: N/A  
Function: N/A  
Production Site: N/A  
Product Label: N/A

## 7 Reference Documents / Attachments

| Kind of document                | Document number | Remarks |
|---------------------------------|-----------------|---------|
| <a href="#">Data Sheet 5216</a> |                 |         |

| 5216 Appliance outlet |            |              |             |                  | 0118.2203 |        |
|-----------------------|------------|--------------|-------------|------------------|-----------|--------|
| creation date         | created by | release date | released by | notification no. | revision  | page   |
| 2014-01-21            | hotzar     | 2014-02-11   | hotzar      | 25633            | -         | 1 of 1 |