



Product Change Notification / MFOL-24SJQF382

Date:

27-Apr-2022

Product Category:

Bluetooth Module, Wireless Modules

PCN Type:

End of Life

Notification Subject:

eSign# E000104918: End of Life (EOL) of RN41xx, RN-27xx, RN42xx, RN52xx and RN-24xx device families.

Affected CPNs:

[MFOL-24SJQF382_Affected_CPN_04272022.pdf](#)
[MFOL-24SJQF382_Affected_CPN_04272022.csv](#)

Notification Text:

PCN Status:End of Life (EOL) Notification

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN_#_Suggested Replacements.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:The RN41xx, RN-27xx, RN42xx, RN52xx and RN-24xx device families will be moving to End of Life (EOL) status effective today. These device families will no longer be offered after the date listed in the attached PCN_#_Suggested_Replacements file. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

Reason for EOL:No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates:Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

Last date for bookings (LTB): Please refer to PCN_#_Suggested_Replacements (excel file) for the list of LTB dates identified per catalog part number.

Last date for shipments (LTS): Please refer to PCN_#_Suggested_Replacements (excel file) for the list of LTS dates identified per catalog part number.

Revision History:April 27, 2022: Issued EOL notification.

Attachments:

[PCN_MFOL-24SJQF382_Suggested Replacements.xlsx](#)
[PCN_MFOL-24SJQF382_Suggested Replacements.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

RN41NAPL-I/RM545
RN-270FDTV
RN-270MGDC010
RN42NAPL-I/RM545
RN42NHCI-I/RM
RN52CVC-I/RM116
RN42NHID-I/RM
RN-270FGDC010
RN52SRC-I/RM100
RN-270F
RN42-I/RMCOS477
RN52UDF-I/RM116
RN52APC-I/RM117
RN42N-I/RMCOS477
RN42NU-I/RM
RN-270M
RN-240FGDC010
RN42U-I/RM
RN-240MGDC010
RN42NAPL-I/RM
RN-240M
RN42-I/RMEVO519
RN-240F
RN41NAPL-I/RM543
RN41N-I/RM615
RN41N-I/RM477
RN41NAPL-I/RM
RN41N-I/RM
RN42XVU-I/RM
RN42SM-I/RM
RN42-I/RMMGK477
RN42N-I/RM477
RN52-I/RM110
RN42-I/RMETI540
RN42HCI-I/RM
RN42APL-I/RM
RN42HID-I/RM
RN42N-I/RM
RN42-I/RM477
RN42-I/RM615
RN42-I/RM630
RN42APL-I/RM543
RN42APL-I/RM545
RN42-I/RM
RN42APL-I/RM550
RN42XVP-I/RM

RN52-I/RM