

End of Life Notification

From time to time we find it necessary to change, modify, or replace our product offering. These changes are usually the result of advancements in technology that offer improvements in performance or manufacturability. Unavailability of component parts, generally of an earlier technology or an older design, can cause the obsolescence of outdated product families.

We sincerely appreciate your business and will make every effort to work with you during your transition to the new power supplies. In some cases of obsolescence, a new advanced model has been introduced to replace the existing power supplies. All products now being discontinued are available for an end-of-life last time buy.

We have recommended a suitable replacement for your convenience on most of the end-of-life models. If you have any questions or need specific application assistance, please contact us (you may visit <https://www.artesyn.com/contact>. Email to productsupport.ep@Artesyn.com or call +1-888-412-7832 - NAM / +44-800-0321546 - EMEA / +86-400-8899-130 - China) or your local sales representative to assist you.

Thank you for your continued patronage.

The following models have been marked as EOL:

Model No	Replacement Model	Replacement Info	LTB Period Start	LTB Period End
73-688-0001			7/10/2018	1/10/2019
LPS22	NPS22-M		12/1/2019	6/30/2020
LPS23	NPS23-M		12/1/2019	6/30/2020
LPS24	NPS24-M		12/1/2019	6/30/2020
LPS25	NPS25-M		12/1/2019	6/30/2020
LPS252-C			12/1/2019	6/30/2020
LPS252-CEF			12/1/2019	6/30/2020
LPS252-CF			12/1/2019	6/30/2020
LPS253-C	CPS253-M		12/1/2019	6/30/2020
LPS253-CEF			12/1/2019	6/30/2020
LPS253-CF			12/1/2019	6/30/2020
LPS254-C			12/1/2019	6/30/2020
LPS254-CEF			12/1/2019	6/30/2020
LPS254-CF			12/1/2019	6/30/2020
LPS255-C	CPS255-M		12/1/2019	6/30/2020
LPS255-CEF			12/1/2019	6/30/2020
LPS255-CF			12/1/2019	6/30/2020
LPT22	NPT42-M		12/1/2019	6/30/2020
LPT23	NPT43-M		12/1/2019	6/30/2020
LPT24	NPT44-M		12/1/2019	6/30/2020
LPT25			12/1/2019	6/30/2020

NFS110-7602J	LPT104-M		12/1/2019	6/30/2020
NFS110-7602PJ	LPT104-M		12/1/2019	6/30/2020
NFS110-7604J	LPT103-M		12/1/2019	6/30/2020
NFS110-7604PJ	LPT103-M		12/1/2019	6/30/2020
NFS110-7901PJ	LPT102-M		12/1/2019	6/30/2020
NFS110-7902PJ	LPT104-M		12/1/2019	6/30/2020
NFS110CJ			12/1/2019	6/30/2020
NFS40-7605J	LPS42		12/1/2019	6/30/2020
NFS40-7607J	LPT44		12/1/2019	6/30/2020
NFS40-7608J	LPT42		12/1/2019	6/30/2020
NFS40-7610J	LPT45		12/1/2019	6/30/2020
NFS40-7612J	LPS43		12/1/2019	6/30/2020
NFS40-7615J	LPS44		12/1/2019	6/30/2020
NFS40-7624J	LPS45		12/1/2019	6/30/2020
NFS40-7628J	LPT43		12/1/2019	6/30/2020
NFS40-76S3J	LPS41		12/1/2019	6/30/2020
NFS40CJ			12/1/2019	6/30/2020
CXA10-48S05J	AEE03A36-LS		10/18/2019	4/17/2020
CXA10-48S05-SJ	AEE03A36-LS	AEE does not have an enable pin	10/18/2019	4/17/2020
CXA10-48S12J	AEE01B36-LS		10/18/2019	4/17/2020
IBC04-36S12-J		No replacement available	10/17/2019	12/31/2019
AVE450-48S32LD	AVE450B-48S28-6L/M		10/17/2019	12/31/2019
AVO100-36S3V3B-6L			10/18/2019	12/31/2019
AVO100-48S1V8-6L			10/18/2019	12/31/2019
AVO100-48S1V8B-6L			10/18/2019	12/31/2019
AVO100-48S1V8P-6L			12/18/2019	12/31/2019
AVO100-48S1V8PB-6L			10/18/2019	12/31/2019
AVO100-48S2V5-6L			10/18/2019	12/31/2019
AVO100-48S2V5B-6L			10/18/2019	12/31/2019
AVO100-48S2V5P-6L			10/18/2019	12/31/2019
AVO100-48S2V5PB-6L			10/18/2019	12/31/2019
AVO100B-48S1V5-6L			10/18/2019	12/31/2019
AVO100B-48S1V5B-6L			9/18/2019	12/31/2019
AVO100B-48S1V5P-6L			10/18/2019	12/31/2019
AVO100B-48S1V5PB-6L			10/18/2019	12/31/2019
ADQ700-48S12B-4LHS			10/18/2019	12/31/2019
ADQ700-48S12B-4LIHS			10/18/2019	12/31/2019
AVO75B-36S3V3-6L			11/6/2019	12/31/2019
AVO75B-36S3V3B-6L			11/6/2019	12/31/2019