

Product End-of-Life Notification Effective Immediately

Sprint Specific Cellular Modems

SocketModem® Cell (MTSMC-LSP3-xx) Dragonfly[™] (MTQ-LSP3-B0x) MultiConnect® microCell (MTCM-LSP3-B03-KIT)

Replacement Models Available

Date: August 17, 2022 (updated)

I. Summary

Due to a critical component End-of-Life, the models listed in this announcement are changing status from **Active** to **End-of-Life (EOL)** effective immediately.

Replacement models are available.

II. Part Numbers Impacted / Recommend Replacement Models

Contents:

I. <u>Summary</u>

- II. Part Numbers Impacted
- III. <u>Key Dates</u>
- IV. Warranty and Support
- V. Suggested Action Plan
- VI. Additional Information

| EOL Ordering Part | UPC | Recommended Replacement | UPC |
|-------------------|--------------|-------------------------|---------------------------|
| Numbers | | Models | |
| | | MTSMC-L4N1.R1A or | 789407375187 |
| MTSMC-LSP3 | 789407366932 | MTSMC-L4N1.R2 | 789407376757 |
| | | MTSMC-L4N1.R1A-SP or | 789407375194 |
| MTSMC-LSP3-SP | 789407366949 | MTSMC-L4N1.R2-SP | 789407376764 |
| | | MTSMC-L4N1-U.R1A or | 789407375200 |
| MTSMC-LSP3-U | 789407366918 | MTSMC-L4N1-U.R2 | 789407376771 |
| | | MTSMC-L4N1-U.R1A-SP or | 789407375217 |
| MTSMC-LSP3-U-SP | 789407366925 | MTSMC-L4N1-U.R2-SP | 789407376788 |
| | | MTQ-LNA7-B02.R1A or | 789407375668 |
| MTQ-LSP3-B02 | 789407367915 | MTQ-LNA7-B02.R2 | 789407375958 |
| | | MTQ-LNA7-B02.R1A-SP or | 789407375675 |
| MTQ-LSP3-B02-SP | 789407367922 | MTQ-LNA7-B02.R2-SP | 789407375965 |
| | | MTCM-LNA3-B03-KIT or | 789407370687 |
| MTCM-LSP3-B03-KIT | 789407369322 | MTCM-LAT3-B03-KIT | <mark>789407369315</mark> |

Please consult with your MultiTech sales support representative for information on which replacement models have the best availability at this time.



III. Key Dates End-of-Life (EOL) Date: August 17, 2022

IV. Warranty and Support

MultiTech will provide technical support and repair or exchange of the products listed in this announcement through the warranty period of the installed device. However, no firmware/software updates or maintenance releases will take place post EOL date.

V. Suggested Action Plan

We recommend the following actions be taken:

- Remove the EOL model numbers from your ordering systems and web sites.
- Forward this announcement to others within your organization who are actively involved in the sale or support of the devices listed in this announcement.
- Notify existing customers who have been using these devices and work to migrate them to one of the recommended replacement models.

VI. Additional Information

If you have any questions or require additional information on this Product End-of-Life Notification, please contact MultiTech customer service:

World Headquarters – U.S.

+1 (763) 785-3500 | <u>cservice@multitech.com</u>

EMEA Headquarters – UK:

+(44) 118 959 7774 | sales@multitech.co.uk

SocketModem, Dragonfly, MultiConnect, MultiTech and the MultiTech logo are registered trademarks of Multi-Tech Systems, Inc. All other trademarks or registered trademarks are the property of their respective owners. Copyright © 2022 by Multi-Tech Systems, Inc. All rights reserved.