

# PRODUCT CHANGE NOTIFICATION

PCN#: COPPER, OUTLETS, SURFACE RACEWAY 20181008-1

ISSUE DATE: 20181015

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Not Required for discontinuation)**

Select Mini-Com® faceplates are being discontinued and replacement parts are listed on the "Part Numbers" tab.

Photos/Drawing (where applicable)

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2019	1	15

**\*Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
CFPTR2BEI	CFPWR4CIG
CFPWR4EI	CFPWR4CIG
CFPWR4IG	CFPWR4CIG
CFPWR4IW	CFPWR4CIG
CFPWR4WH	CFPWR4CIG
CFPWR4BL	CFPWR4CIG