

## **PRODUCT DISCONTINUATION NOTICE**

PDN No.: USA 2018-002

IXYS PRODUCT TYPE		TYPE: 85V P CHANNEL POLAR MOSFET		ECOMMEND REPLACEMENT	:
XT*50P085				IXTT50P10	
REASON FOR DISCONTIN	UATION: <b>OBSOLE</b>	TE TECHNOLOGY ,	LACK OF DEI	MAND	
LAST TIME ORDER DATE: LAST TIME DELIVERY DA		WITH THE FACTORY WITH THE FACTORY			
NTERNAL REFERENCE:	N/A				
	TITLE/FUNC DEPT HEAD	TION [	DATE FEBRUARY 28,	E-MAIL , 2018 G.ROSETE@IXYS.N	ET
GORDON ROSETE	DEPT HEAD				ET
GORDON ROSETE CUSTOMER RESPONSE	DEPT HEAD	QA, IXYS MILPITAS			ET
GORDON ROSETE CUSTOMER RESPONSE	DEPT HEAD	QA, IXYS MILPITAS	FEBRUARY 28,		
INITIATOR GORDON ROSETE  CUSTOMER RESPONSE (PLEASE FILL IN AND RETURN E  for further question please comment	DEPT HEAD	QA, IXYS MILPITAS  ITHIN 4 WEEKS)  Company:  Name & Position	FEBRUARY 28,	, 2018 G.ROSETE@IXYS.N	
GORDON ROSETE  CUSTOMER RESPONSE  (PLEASE FILL IN AND RETURN E  for further question  please comment	DEPT HEAD  E: BY E-MAIL, FAX OR MAIL W  Ins/ information	QA, IXYS MILPITAS  ITHIN 4 WEEKS)  Company:  Name & Position  Phone / Fax No:	FEBRUARY 28,	, 2018 G.ROSETE@IXYS.N	
GORDON ROSETE  CUSTOMER RESPONSE  (PLEASE FILL IN AND RETURN E  for further question	DEPT HEAD  E: BY E-MAIL, FAX OR MAIL W  Ins/ information	QA, IXYS MILPITAS  ITHIN 4 WEEKS)  Company:  Name & Position  Phone / Fax No:	FEBRUARY 28,	, 2018 G.ROSETE@IXYS.N	