



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

(06/23/2021)

Obsolescence of 55110 series

Dear Valued Customer,

Littelfuse would like to notify you of the obsolescence of our 55110 series, due to the obsolescence of the key component – Hall effect switch.

The following part numbers are affected:

55110-3H-02-A
55110-3H-02-F
55110-3H-05-A
55110-3M-02-A
55110-3M-02-F
55110-3M-03-A
55110-3M-05-A

There is no direct replacement. Due to the immediate obsolescence of the component, we are not in a position to offer a LTB.