

1 Products affected


Product hierarchy no. *			archy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Туре				
		025	000000550	0031.8241	Circuit protection		n/a
04	002			0031.8241.F1		Fuseholder OGD-SMD	n/a
U				0031.8242		ruseriolder OGD-SiviD	n/a
				0031.8242.F1			n/a

^{*}SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Modified label
- Change of markings

3 Detailed description of change



4 Reason of change

Adjusted product markings acc. to current standard and approvals.

5 Release date

The change will be rolled-out starting ww 09/2017 (date code 1709 on label) and lasts approx. 4 months.

Product Change Notification					Inscription change OGD-SMD			
owner	creation date	release date	released by	change order no	rev	page	D40 040 050	
dislercy	2017-01-23	2017-02-22	nowakfr	2011941	Α	1 of 2	D10-012-850	



6 Impact of change and recommended action

Form Yes Inscription on socket changed
Fit No No change for dimension
Function No No functional change

Manufacturing No No change for manufacturing site

Label Yes Approvals and configuration code on label

Packaging No No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification					Inscription change OGD-SMD			
owner	creation date	release date	released by	change order no	rev	page	D40 040 050	
dislercy	2017-01-23	2017-02-22	nowakfr	2011941	Α	2 of 2	D10-012-850	