

PRODUCT DISCONTINUATION NOTICE

PDN No.: USA 2012-068

| IXYS PRODUCT TYPE: | TYPE: | | RECOMMEND REPLACEMENT: |
|--|--|----------------------------------|--|
| SPECIAL PART NUMBER (S IXYS GENERIC: IXBV20N3 IXFV12N120PS,IXFV110 IXFV12N90PS, IXFV16N8 IXFV36N50PS, IXFV52N IXGV25N250S, IXTV02N IXTV03N400S, IXTV110N IXTV22N50PS, IXTV250I IXTV270N055T2S, IXTV2 | 800 Surfa N10PS 0PS 30PS 250S N25TS N075TS | S & TO220PS HV ace Mount Package | NO RECOMMENDATION |
| REASON FOR DISCONTINUATION | LACK OF DEMA | AND FOR THE PRODUC | T |
| LAST TIME ORDER DATE: DEC | 2013 | | |
| LAST TIME DELIVERY DATE: DEC | 2014 | | |
| INTERANAL REFERENCE: N/A | | | |
| | | | |
| In case of any question, please cont | | | |
| INITIATOR: | TITLE/FUNCTION: QA ENGINEER | DATE: 12/03/20 ² | E-MAIL: 12 T.NGUYEN@IXYS.NET |
| THU NGUYEN | Q . (= (0) (1) | .=,00,=0 | |
| N/L | | | |
| <u> </u> | | | |
| | | | |
| CUSTOMER RESPONSE: | | | |
| (PLEASE FILL IN AND RETURN BY E-MAIL | , FAX OR MAIL WITHIN 4 W | EEKS) IXYS CORPORATI | ON 1590 BUCKEYE DRIVE, MILPITAS CA 95035 |
| for further questions/ infor | mation | Company: | |
| please comment | | Name & Position | |
| | | Phone / Fax No: | |
| COMMENTS: | | | |
| | | | |
| IF 0266 Rev.0 (01.26.10) | | Page 1 of 1 | Reference QS 0073 |

Rev.0 (01.26.10)

IF 0266