UNCONTROLLED DOCUMENT

PART NUMBER


REV.

CLS-R011A12250R


DATE


\ L V	Š	140MDEL	7110
Α	E.C.N.	#11148.	


RFV. | E.C.N. NUMBER AND REVISION COMMENTS 12.08.06



CHARACTERISTICS \		
RATING	30A AT 12VDC	
LED COLOR	RED	
CIRCUIT OPERATION	SPST	
NO. OF PINS	3	
SWITCH OPERATION	ON-OFF	







UNCONTROLLED DOC

*UNLESS DTHERWISE SPECIFIED TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0.039), XXX=±0.5 (±0.020), XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.010). MN= +DECINAL PRECISION MAX.= +0.00 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.010). MN=+DECINAL PRECISION MAX.= +0.00 (±0.005).

REV. PART NUMBER CLS-R011A12250R

> RED LED, ILLUMINATED, OVAL ROCKER SWITCH, RATED FOR 30A AT 12V.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF
LUMEX NO. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX
INC. THE RANDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION
CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

 $\begin{array}{c} \underline{\text{Reliablity Note}} \\ \text{Our nany years of experience data accumulation indicate that} \end{array}$ SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

290 E. HELEN ROAD PALATINE, IL 60067—6976 PHONE; +1.847.359,2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DRAWN BY: CHECKED BY: APPROVED BY: DATE: 12.08.06 PAGE: OF 1 SCALE: N/A JC