

PDN No: 16-0519-01 Issue Date: 23-AUGUST-2016

Subject: Product Discontinuation Notification

To whom it may concern,

This is notification that the part numbers listed below will be discontinued by Exar Corporation:

| Ordering Part Number | Suggested Part Replacement | Pin Compatible | Comments |
|-------------------------|---------------------------------------|----------------|-------------------------------------|
| SP3232EUEN-L | SP3232EUEA-L/TR or SP3232EUEY-L/TR | Yes | Package change |
| SP1485EMN-L/TR | SP1485EEN-L/TR | Yes | Industrial temp range |
| SP3243EHEY-L/TR | SP3243EHEA-L/TR | Yes | Package change (from TSSOP to SSOP) |
| SP3243EHEY-L | SP3243EHEA-L/TR | Yes | Package change (from TSSOP to SSOP) |
| SP3243EHCY-L/TR | SP3243EHCA-L/TR | Yes | Package change (from TSSOP to SSOP) |
| SP3243EHCY-L | SP3243EHCA-L/TR | Yes | Package change (from TSSOP to SSOP) |

Purchase orders will be accepted as indicated below on a non-cancellable, non-returnable basis provided there is inventory remaining at the time of order placement. ** Subject to product availability. No reschedules will be allowed.

| Last order date: | February 23, 2017 |
|------------------|-------------------|
| Last ship date: | August 23, 2017 |

Please check inventory availability with your distributor or Exar Customer Service Representative before attempting to place an order.

Note to distributors: All LTB purchase orders must be submitted manually.

If you should have any questions regarding this notice, please contact Lisa Bedard via email at Lisa.Bedard@Exar.com or customersupport@exar.com.