



English



Search ...

PRODUCTS | APPLICATIONS | DESIGN SUPPORT | TRAINING | SAMPLE AND BUY | ABOUT
US | CONTACT US | myMicrochip Login

Product Change Notification - JAON-22LLUU358 (Printer Friendly)

Date: 29 Sep 2015

Product Category:

Notification subject: End of Life (EOL) of MIC1344, MIC23163, MIC23164, MIC2786, MIC2787, MIC2788, MIC2789, MIC33163, MIC33164, MIC33263, MIC33264, MIC37110, MIC37112, MIC37120, MIC37122 MIC4520 and MIC4521 device families

Notification text: **PCN Status:**
End of Life (EOL) notification

Microchip Parts Affected:

Please open the attachments found in the attachments field below labeled as PCN_#_Affected_CPN.

Description of EOL:

The MIC1344, MIC23163, MIC23164, MIC2786, MIC2787, MIC2788, MIC2789, MIC33163, MIC33164, MIC33263, MIC33264, MIC37110, MIC37112, MIC37120, MIC37122, MIC4520 and MIC4521 device families will be moving to End of Life (EOL) status effective today. These device families will no longer be offered after September 30, 2016. Replacement parts, if available, are listed in the affected part numbers attachments. Please observe the notes, in the attachment, regarding the replacement parts to identify differences between the EOL CPN and the replacements.

Reason for EOL:

Manufacturing capability for the CPNs listed in the attachment being phased out.

Estimated Effective Dates:

Customers affected by this EOL notice are advised to place last time buy orders (LTB) as follows:
Last date for bookings (LTB): March 31, 2016.
Last date for shipments (LTS): September 30, 2016.

Revision History:

September 29, 2015: Initial release of notification.

Attachment(s): [PCN_JAON-22LLUU358_Affected_CPN.pdf](#)
[PCN_JAON-22LLUU358_Affected_CPN.xls](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."



Products | Applications | Design Support | Training | Sample and Buy | About Us |
Contact Us | Legal | Investors | Careers | Support

JAON-22LLUU358 - End of Life (EOL) of MIC1344 MIC23163 MIC23164 MIC2786, MIC2787, MIC2788, MIC2789, MIC33163, MIC33164, MIC33263, MIC33264, MIC37110, MIC37112, MIC37120, MIC37122, MIC4520 and MIC4521 device families

Affected Catalog Part Numbers (CPN)

PCN_JAON-22LLUU358		
EOL Catalog Part Number (CPN)	Recommended Replacement	Notes About the Recommended Replacement
MIC37110-1.8YM	MIC69101-1.8YML	Not Drop in Replacement Contact your local sales office
MIC37110-1.8YM-TR	MIC69101-1.8YML	Not Drop in Replacement Contact your local sales office
MIC37110-1.8YMT-TR	MIC69101-1.8YML	Not Drop in Replacement Contact your local sales office
MIC37110-1.8YS	MIC69101-1.8YML	Not Drop in Replacement Contact your local sales office
MIC37110-1.8YS-TR	MIC69101-1.8YML	Not Drop in Replacement Contact your local sales office
MIC37112YM	MIC69103YML	Not Drop in Replacement Contact your local sales office
MIC37112YM-TR	MIC69103YML	Not Drop in Replacement Contact your local sales office
MIC37112YMT-TR	MIC69103YML	Not Drop in Replacement Contact your local sales office
MIC37120-1.8YMT-TR	MIC69101-1.8YML	Not Drop in Replacement Contact your local sales office
MIC37122YM	MIC69103YML	Not Drop in Replacement Contact your local sales office
MIC37122YM-TR	MIC69103YML	Not Drop in Replacement Contact your local sales office
MIC37122YMT-TR	MIC69103YML	Not Drop in Replacement Contact your local sales office
MIC2786-XAYMT-TR	MCP1316-MCP1321	Family of Voltage Supervisors --- Close Functional Contact your local sales office
MIC2786-XDYMT-TR	MCP1316-MCP1321	Family of Voltage Supervisors --- Close Functional Contact your local sales office
MIC2787-XAYMT-TR	MCP1316-MCP1321	Family of Voltage Supervisors --- Close Functional Contact your local sales office
MIC2787-XDYMT-TR	MCP1316-MCP1321	Family of Voltage Supervisors --- Close Functional Contact your local sales office
MIC2788-XYMT-TR	MCP1316-MCP1321	Family of Voltage Supervisors --- Close Functional Contact your local sales office
MIC2789-XYMT-TR	MCP1316-MCP1321	Family of Voltage Supervisors --- Close Functional Contact your local sales office
MIC23163YMT-T5	MIC23153YMT	Not Drop in Replacement Contact your local sales office
MIC23163YMT-TR	MIC23153YMT	Not Drop in Replacement Contact your local sales office
MIC23164YMT-T5	MIC23153YMT	Not Drop in Replacement Contact your local sales office
MIC23164YMT-TR	MIC23153YMT	Not Drop in Replacement Contact your local sales office
MIC33163YGJ-T5	MIC23155YMT	Not Drop in Replacement Contact your local sales office
MIC33163YGJ-TR	MIC23155YMT	Not Drop in Replacement Contact your local sales office
MIC33164YGJ-T5	MIC33153YHJ	Not Drop in Replacement Contact your local sales office

JAON-22LLUU358 - End of Life (EOL) of MIC1344 MIC23163 MIC23164 MIC2786, MIC2787, MIC2788, MIC2789, MIC33163, MIC33164, MIC33263, MIC33264, MIC37110, MIC37112, MIC37120, MIC37122, MIC4520 and MIC4521 device families

Affected Catalog Part Numbers (CPN)

MIC33164YGJ-TR	MIC33153YHJ	Not Drop in Replacement Contact your local sales office
MIC33263YGK-T5	Contact your local sales office	NA
MIC33263YGK-TR	Contact your local sales office	NA
MIC33264YGK-T5	Contact your local sales office	NA
MIC33264YGK-TR	Contact your local sales office	NA
MIC1344YFT-T5	Contact your local sales office	NA
MIC1344YFT-TR	Contact your local sales office	NA
MIC4520YFL-T5	Contact your local sales office	NA
MIC4520YFL-TR	Contact your local sales office	NA
MIC4521YFL-T5	Contact your local sales office	NA
MIC4521YFL-TR	Contact your local sales office	NA