



Product Discontinuance Notice - PDN 18_0060 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of HMC products due to loss of manufacturing and supply capability.

Publication Date: 05-Oct-2018

Last Time Buy Date: 15-Mar-2019

Last Time Ship Date: 15-Mar-2020

Revision Description:

Initial Release

Reason For Discontinuance

Loss of manufacturing and supply capability.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 18_0060 Discontinued Parts Material List

| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
|-------------------|----------------|-------------------|-----------------------|----------|
| 126674-HMC847LC5 | HMC847 | 126578-HMC854LC5 | No | |
| 126674-HMC848LC5 | HMC848 | 126578-HMC855LC5 | No | |
| 128921-HMC843LC4B | HMC843 | 118777-HMC722LC3C | No | |
| 128921-HMC844LC4B | HMC844 | 125614-HMC851LC3C | No | |
| 129126-HMC841LC4B | HMC841 | 125614-HMC853LC3 | No | |
| 129151-HMC842LC4B | HMC842 | 125614-HMC850LC3 | No | |
| HMC1027BG | HMC1027 | ADN4612ACPZ | No | |
| HMC1027BGTR | HMC1027 | ADN4612ACPZ | No | |
| HMC1068 | HMC1068G | none | n/a | |
| HMC1068-SX | HMC1068G | none | n/a | |
| HMC1069 | HMC1069G | none | n/a | |
| HMC1069-SX | HMC1069G | none | n/a | |
| HMC6545LP5E | HMC6545 | none | n/a | |
| HMC6545LP5ETR | HMC6545 | none | n/a | |
| HMC6590 | HMC6590G | none | n/a | |
| HMC6590-SX | HMC6590G | none | n/a | |
| HMC7282B | HMC7282BG | none | n/a | |

| HMC7545ABLP47E | HMC7545 | none | n/a | |
|------------------|----------------|------------------|-----------------------|----------|
| HMC7545ABLP47ETR | HMC7545 | none | n/a | |
| HMC7590 | HMC7590G | none | n/a | |
| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
| HMC7590-SX | HMC7590G | none | n/a | |
| HMC841LC4B | HMC841 | HMC853LC3 | No | |
| HMC841LC4BTR | HMC841 | HMC853LC3TR | No | |
| HMC841LC4BTR-R5 | HMC841 | HMC853LC3TR-R5 | No | |
| HMC842LC4B | HMC842 | HMC850LC3 | No | |
| HMC842LC4BTR | HMC842 | HMC850LC3TR | No | |
| HMC842LC4BTR-R5 | HMC842 | HMC850LC3TR-R5 | No | |
| HMC843LC4B | HMC843 | HMC722LC3C | No | |
| HMC843LC4BTR | HMC843 | HMC722LC3CTR | No | |
| HMC843LC4BTR-R5 | HMC843 | HMC722LC3CTR-R5 | No | |
| HMC844LC4B | HMC844 | HMC851LC3C | No | |
| HMC844LC4BTR | HMC844 | HMC851LC3CTR | No | |
| HMC844LC4BTR-R5 | HMC844 | HMC851LC3CTR-R5 | No | |
| HMC847LC5 | HMC847 | HMC854LC5 | No | |
| HMC847LC5TR | HMC847 | HMC854LC5TR | No | |
| HMC847LC5TR-R5 | HMC847 | HMC854LC5TR-R5 | No | |
| HMC848LC5 | HMC848 | HMC855LC5 | No | |
| HMC848LC5TR | HMC848 | HMC855LC5TR | No | |
| HMC848LC5TR-R5 | HMC848 | HMC855LC5TR-R5 | No | |

Appendix A - PDN 18_0060 Revision History

| Rev | Publish Date | Rev Description |
|--------|--------------|-----------------|
| Rev. - | 05-Oct-2018 | Initial Release |

Analog Devices, Inc. Proprietary Information

DocId:1295 Layout Rev:2 Parent DocId:None