



## Customer Information Notification

201910019I

**Issue Date:** 01-Nov-2019  
**Effective Date:** 02-Nov-2019

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online



**This notice is NXP Company Proprietary.**

# QUALITY

### Management Summary

PCA9575HF PCB footprint was corrected from 40 pads to 24 pads. Attached data sheet reflects the update.

### Change Category

- |                                              |                                                                                  |                                                    |                                         |                                                         |
|----------------------------------------------|----------------------------------------------------------------------------------|----------------------------------------------------|-----------------------------------------|---------------------------------------------------------|
| <input type="checkbox"/> Wafer Fab Process   | <input type="checkbox"/> Assembly Process                                        | <input type="checkbox"/> Product Marking           | <input type="checkbox"/> Test Location  | <input type="checkbox"/> Design                         |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials                                      | <input type="checkbox"/> Mechanical Specification  | <input type="checkbox"/> Test Process   | <input type="checkbox"/> Errata                         |
| <input type="checkbox"/> Wafer Fab Location  | <input type="checkbox"/> Assembly Location                                       | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input type="checkbox"/> Electrical spec./Test coverage |
| <input type="checkbox"/> Firmware            | <input checked="" type="checkbox"/> Other - Data Sheet - PCB Footprint Corrected |                                                    |                                         |                                                         |

Correct Footprint for Solder Reflow - PCA9575HF

### Description

PCA9575HF PCB footprint was corrected from 40 pads to 24 pads. Attached data sheet reflects the update.

### Reason

PCB drawing needs to reflect the 24 pin package

### Identification of Affected Products

Product identification does not change

### Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

### Data Sheet Revision

A new datasheet will be issued

### Disposition of Old Products

Existing inventory will be shipped until depleted

## Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

**Name** Andrea Bruton  
**Position** QA Analyst  
**e-mail address** andrea.bruton@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

## About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[NXP](#) | [Privacy Policy](#) | [Terms of Use](#)

NXP Semiconductors  
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.

Changed Orderable Part#	Changed Part 12NC	Changed Part Number	Changed Part Description	Package Outline	Package Name	Status	Product Line	Notes
PCA9575HF,118	935286416118	PCA9575HF	PCA9575	SOT994-1	HWQFN24	RFS	High Performance Analog	PCA9575HF