
Notice of Discontinuation for TAIYO YUDEN (U.S.A.) Inc. Distributors

DATE: February 4th, 2022

RE: Discontinuation of Common Mode Choke Coils

REF NO.: UTY-DN22-02D

TAIYO YUDEN (U.S.A.) Inc. hereby gives notice that the following part numbers are to be discontinued **2/4/2022** for all TAIYO YUDEN (U.S.A) Inc. distributors. Please note that any last time buys must be made on or before **5/4/2022**, with a last time ship date of **2/4/2023**. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

Discontinued Part Numbers
BU05MC01T
BU05MC08T
TLF9UBH302WK1
TLF9UB302WK1
TLF9UBH802WK1
TLF9UB802WK1
TLF9UBH203WK1
TLF9UB203WK1
TLH10UA9012R0
TLH10UA1121R8
TLH10UA1521R6
TLH10UA2121R4
TLH10UA2821R2
TLH10UA4321R0
TLH10UA6220R8
TLH10UA8720R7
TLH10UA9920R6
TLH10UA1430R5
TLH10UB7012R0
TLH10UB1121R7
TLH10UB1421R4
TLH10UB2321R2
TLH10UB3521R0
TLH10UB4420R8
TLH10UB8720R7
TLH10UB9720R6
TLH10UB1130R5
TLF9UA102W0R8K1
TLF9UA202WR54K1
TLF9UA302WR42K1
TLF9UA502WR32K1
TLF9UA802WR25K1
TLF9UA103WR23K1
TLF9UAH102W0R8K1
TLF9UAH202WR54K1
TLF9UAH302WR42K1
TLF9UAH502WR32K1
TLF9UAH802WR25K1
TLF9UAH103WR23K1

NOTE: The information in this notice is applicable only to TAIYO YUDEN (U.S.A.) Inc. distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the TAIYO YUDEN sales office responsible for sales in your country for details on this notice.