

## Datasheet

standexelectronics.com

# S12R-SSRDSO-NOSL5-500 Gear Tooth Speed Switch

- Ferrous target activated Speed Switch
- > 8 to 32V DC Powered
- > 150 VAC Normally Open Form A Relay
- Stainless 12x1mm x 45mm housing
- Shielded 2 pair 22 AWG 105°C PVC, 5 foot



# CUSTOMER FOCUSED ENGINEERING + MODULAR DESIGN -



#### Modify, update, or enhance any sensor with our modular features and functionality.

*HOUSING* - Aluminum, stainless steel, plastic, threaded, flange mount, customer specific

**ELECTRICAL** - Every sensor function available in various electrical options (NPN, PNP, TTL, etc.) **CONNECTION -** Deutsch, Amphenol, many other brands, free end wires, pigtails, any length

Need a Custom Sensor Solution?... Send us your application specific requirements at sensorso.com

# 'Steel Gears & Ferrous Target Actuated Speed Switch with <u>Relay Output</u>' Overspeed, Underspeed, Zero-Speed



# OUTPUTS



### DESCRIPTION

- Speed switch output turns on/off dependent on factory programmed frequency.
- 500 Hz switch point functions as "0 speed" indicator. For other switch speeds contact Sensor Solutions.
- Single channel digital square wave output for resolving actual speed.
- Detects gears and other ferrous targets using Hall Effect Technology
- Capable of detecting 0-32 pitch gears, bolt heads, holes in steel plates, and other ferrous targets
- No orientation required. Use lock nuts to set air gap within range of target

## FEATURES

- Ferrous Target Speed Switch
- No Orientation Required
- Add –xxx in Hz to End of PN contact factory for custom switch point models





### Datasheet

# S12R-SSRDSO-NOSL5-500 Gear Tooth Speed Switch

### **OTHER OPTIONS**

As well as these Ferrous Target Speed Switches, we offer Magnet / Magnet Tape activated Speed Switches, and Gear Tooth Speed Switches designed to work with standard gears. We have options for relay outputs, NPN outputs, and TTL outputs.

Note: Check our website or contact us to discuss any of our magnetic speed, count, and position detection sensors.

<b>Electrical Specifications</b>	Conditions	Min	Max	Unit
Temperature Range	Operating	-40	+110	Deg C
Supply Voltage, Vcc	Over temperature	+8	+32	Volts DC
Supply Current	Into Vcc	6	24	mA
Contact Resistance	Initial	-	0.10	Ohms
<b>Overspeed TRIP Frequency</b> 100% Final Tested at factory	Output goes low above	490	505	Hz
<b>Underspeed Release Freq.</b> 100% Final Tested at factory	Output goes high below	470	485	Hz
Relay Closing Bounce Time	T=25C	-	3	mS
ESD (like product qualified)	Nondestructive	-	2000	Volts
EMI (like product qualified)	20k to 1 G Hz	-	20	V/M
				Rev C



#### SL5, Ind. Shielded 2 Pair 22 AWG -20 to 105°C PVC



# standexelectronics.com

Absolute Max Limits	Min	Max	Unit
Supply Voltage, Vcc-Gnd	-16	+32	Volts
Voltage at Relay	-	150	Volts AC
Voltage at Relay	-	120	Volts DC
Switching Current, T = 25C	-	1	Amp
Switching Current, T = 70C	-	.45	Amp
Switching Power, T = 25C	-	30	Watts
Isolation, Surge Voltage Between Supply and Relay	-	1.5	k Volts

Environmental Specifications		
<b>Corrosion Resistance</b>	500 hours salt spray ASTM B-117	
Installation Torque	23 Foot-Pounds Maximum	
Enclosure	Nema 1,3,4,6,13 & IEC IP67	
Vibration	10 G's 2 to 2000 Hz Sinusodal	
Mechanical Shock	100 G's, 11 mS Half-Sine	

#### Sensor Characteristics

Output State at 0 Speed: Relay Open

Air Gap Range, Targets	Min	Тур	Max
Large >1/4" wide and >1/4" apart	.000″	.070″	.140"*
Med. >1/8" wide and >1/8" apart	.000″	.045″	.080″*
Small >1/16"wide and >1/8" apart	.000″	.028″	.030″*
8 Pitch Gear (.393" tooth to tooth)	.000″	.015″	.085″*
<b>TRIP Frequency</b> Accuracy, Output <b>LOW</b>	.98%	1.0%	1.01%*
RELEASE Frequency Accuracy, Output HIGH	.99% <b>***</b>	1.0%	1.02%
STOP DETECT TIME, Output returns high after sudden stop	10	ms (Typic	cal)

\* Gap the sensor less than MAX GAP.

\*\* Relay is guaranteed CLOSED if teeth are passing by faster than 1.02 \* Trip Frequency.

\*\*\*Relay is guaranteed OPEN if teeth are passing by slower than 0.99 \* Release Frequency

#### Convert RPM to Hz

Over/Under Speed Trip Points are in Hz, pulses per second.

To convert RPM (Revolutions per Minute) to Hz, you need to know the target's pulses per revolution, "N". A 20-tooth target produces 20 pulses, so N=20.

# Hz = RPM \* (N / 60). Or RPM = Hz \* (60 / N).

*Example:* For a 20-tooth target and 500 Hz trip point, RPM = 500 \* (60 / 20) so the output switches low at 1500 RPM.

Connections Chart	
Red Vcc	Black Ground
White Relay Output	Green Relay Common
9	SL5-SSRDSO
OTHER MATING CON	NECTORS AND CABLES AVAILABLE



### Datasheet

standexelectronics.com

# S12R-SSRDSO-NOSL5-500 Gear Tooth Speed Switch





Please note: All technical specifications on this series datasheet refer to the standard product range. Modifications in the sense of technical progress are reserved. For general information only. For more specific information, please consult the product datasheet, available upon request.

This series datasheet could contain technical inaccuracies or typographical errors. Changes are periodically made to the information herein. These change will be incorporated in future revisions.

For deviating values, most current specifications and products please contact your nearest sales office.