

Global Change Notification (GCN)

Product Family	iPass+HD	10667857
		GCN Number
Series	76867	January 07, 2015
		Date Issued
Reason For Change	Change Construction Or Material	
Change Description	This letter is to inform you that to reduce the risk of cracking, there will be a change to the material used for iPass+HD internal latch frames from LCP to PBT for series 76867. The old LCP latch frame part numbers 76993-0001,-0002 and -0003 will be obsolete and replaced with new part numbers for the PBT versions; 76993-1000,-2000 and -3000.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes	
Assessment Of Change (How Product Will Be Qualified & Validated)	Product with new material will be validated by product engineer.	
Internal Molex Qualification Date (Planned Date Information Available)	February 13, 2015	
Sample Availability Date (Changed Part)	February 16, 2015	
Date of Implementation	February 20, 2015	
Method of Identifying Change	W/O # and Green Dot on manufacturing label	
Recommended Replacement Parts	Replacements part numbers listed above	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com