



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M001045

DATE: 11-Nov-2021

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX6769TALD2/V+T	N/A			Part reactivated from prior notice: M000886
Discontinuance	DS1847E-050+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	DS28E02P-W13+1T	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	DS4830T+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX146ACPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX146BCPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX147BCPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX148BEPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX15511GTL+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX15511GTL+QT	N/A	13-May-2022	13-May-2022	Part can no longer be manufactured
Discontinuance	MAX15511GTL+T	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	MAX160EPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX16405GKM+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX16405GKM+T	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX218CPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX222CPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX222EPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX242CPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX242EPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX275ACPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX275AEPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX275BCPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX275BEPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3218CPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3223CPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3223ECPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 12-Dec-2021

Discontinuance	MAX3223EEPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3223EPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3224ECPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3224EEPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3225CPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3225EEPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX3264CUE+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX3264CUE+T	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX3265CUB+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX333CPP+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX40213AWA+	MAX40213EWA+	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	MAX40213AWA+T	MAX40213EWA+T	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	MAX5022EUA+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX5062BASA+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX563CPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX620CPN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX638AEP+	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	MAX732CWE+T	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX732EWE+T	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX752CWE+T	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX798ESE+	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	MAX798ESE+T	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	MAX8770GTL+	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	MAX9323EUP+	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX9323EUP+T	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAX9323EUP+T	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAXQ1062ETP+	MAXQ1061ETP+	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAXQ1062EUD+	MAXQ1061EUD+	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MAXQ1062EUD+T	MAXQ1061EUD+T	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	MX7528JN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MX7528KN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MX7574JN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	MX7574KN+	N/A	13-May-2022	09-Nov-2022	Part can no longer be manufactured
Discontinuance	PHY1092-01DS-FR	N/A	11-Nov-2021	11-Nov-2021	Part can no longer be manufactured
Discontinuance	PHY1092-01DS-WR	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1331SFCX	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 12-Dec-2021

Discontinuance	VT1334SFCX	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	VT1547MBFQ	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1547MBFQ-008	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1547MBFQX	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1547MBFQX-008	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1547MGFQ	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1547MGFQX	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1577MAFQ	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT1577MAFQX	N/A	11-Nov-2022	10-May-2023	Part can no longer be manufactured
Discontinuance	VT382BFCX-ADJ-001	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured
Discontinuance	VT387BFCX-ADJ	N/A	11-Nov-2021	10-May-2022	Part can no longer be manufactured