



QX32P-SW388 Connector Product Obsolescence

DESCRIPTION OF CHANGE: The Vishay Connectors QX32P-SW388 is becoming obsolete, effective immediately.

REASON FOR CHANGE: Vishay no longer has the ability to perform the acceptance testing required.

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: N/A

PART NUMBERS/SERIES/FAMILIES AFFECTED: QX32P-SW388

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Last Time Buy Date: Mon Feb 22, 2021

Last Time Ship Date: Mon Feb 22, 2021

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Wed Mar 24, 2021 or as specified by contract.

ISSUED BY: Doug Lillie, doug.lillie@vishay.com

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

Americas

Vishay Intertechnology, Inc
1505 East Highway 50 P. O. Box 180
Yankton, South Dakota United States 57078
doug.lillie@vishay.com
Phone: 16056659301
Fax: 16056651627

Europe

Vishay Electronic GmbH
Dr Felix Zandman Platz 1
Selb Germany 95100
jens.walther@vishay.com
Phone: 499287712282
Fax: 499287712496

Asia

Vishay Asia Pte
25 Tampines Street 92 Keppel Building #02-00
Singapore Singapore 528877
victor.goh@vishay.com
Phone: +657886668
Fax: +657883383

Vishay Intertechnology, Inc.

Corporate Headquarters 63 Lincoln Highway, Malvern, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com

ONE OF THE WORLD'S LARGEST MANUFACTURERS OF DISCRETE SEMICONDUCTORS AND PASSIVE COMPONENT



Product Change Notification



Product Group: Vishay Dale/February 17, 2021/PCN-DI-00510-2021 Rev 0

QX32P-SW388 Connector Product Obsolescence

DESCRIPTION OF CHANGE: The Vishay Connectors QX32P-SW388 is becoming obsolete, effective immediately.

CLASSIFICATION OF CHANGE: Product Obsolescence

REASON FOR CHANGE: Vishay no longer has the ability to perform the acceptance testing required.

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: N/A

PRODUCT CATEGORY: Connectors

PART NUMBERS/SERIES/FAMILIES AFFECTED:
QX32P-SW388

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Start Shipment Date: N/A

Last Time Buy Date: NA

Last Time Shipment Date: NA

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

ISSUED BY: Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas

Vishay Intertechnology, Inc
1505 East Highway 50
P. O. Box 180
Yankton, South Dakota 57078
Ph: 1 605-665-9301
Fax: 1 605-665-1627
doug.lillie@vishay.com

Europe

Vishay Electronic GmbH
Dr.-Felix-Zandman-Platz 1
95100 Selb
Germany
Ph: 49-9287-71-2282
Fax: 49-9287-71-2496
jens.walther@vishay.com

Asia

Vishay Asia Pte Ltd.
25 Tampines Street 92
Keppel Building #02-00
Singapore 528877
Ph: +65-788-6668
Fax: +65-788-3383
victor.goh@vishay.com

Vishay Intertechnology, Inc.

Corporate Headquarters 63 Lincoln Highway, Malvern, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com

ONE OF THE WORLD'S LARGEST MANUFACTURERS OF DISCRETE SEMICONDUCTORS AND PASSIVE COMPONENT

Procedure #