



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000758I

DATE: 21-May-2013

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1267-050	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267-100	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267E-100	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267E-100/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267E-50	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267E-50/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267S-050	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267S-050/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1267S-100/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1642-70+	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868-100	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868-50	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868E-050/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868E-100	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868E-100/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868E-100/T&R/C1	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868E-50	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868S-050/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868S-100	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868S-100/T&R	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868S-50	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	DS1868S-50+T&R	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	DS87001-E44	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	DS87001-E52	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	DS87001-F80	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	DS87001-Q44	N/A	21-May-2013	21-May-2015	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Jun-2013

Discontinuance	DS87001-Q52	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	DS87001-Q68	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX100CFR	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX100CFR-T	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX100CFR1	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX100CFR1-T	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX100EVKIT	N/A	21-May-2013	21-May-2015	EVKIT is No Longer Supported
Discontinuance	MAX101ACFR	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR-T	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR-TW	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR-W	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR1	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR1-B50017	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR1-T	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR1-TW	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101ACFR1-W	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX101AEVKIT	N/A	21-May-2013	21-May-2015	EVKIT is No Longer Supported
Discontinuance	MAX44009EVKIT+	N/A	21-May-2013	21-May-2015	EVKIT is No Longer Supported
Discontinuance	MAX7370ATG+	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX7370ATG+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX8967AEWV+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX8967BEWV+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX8967CEWV+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX8967EVKIT#	N/A	21-May-2013	21-May-2015	EVKIT is No Longer Supported
Discontinuance	MAX8967EWV+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX9124ESE+T	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX9124EUE+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX9124EUE-T	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX9125ESE+T	N/A	21-May-2013	21-May-2015	Part can no longer be manufactured
Discontinuance	MAX9126ESE+	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX9126ESE+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX9126EUE+	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX9126EUE+T	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAX9934EVKIT+	N/A	21-May-2013	21-May-2015	EVKIT is No Longer Supported
Discontinuance	MAXQ1011-A01+	N/A	21-May-2013	21-May-2015	The part was not released
Discontinuance	MAXQ1012-A01+	N/A	21-May-2013	21-May-2015	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Jun-2013

Discontinuance	MAXQ3160-EAN+	N/A	21-May-2013	21-May-2015	The part was not released
----------------	---------------	-----	-------------	-------------	---------------------------