

PCN-237736

# **Product Change Notice**

Issue Date: 17-September-2021

<u>Change Type:</u> Alternate manufacturing site for ChipLED part numbers listed below.

## Parts Affected:

HSMG-C240 HSMY-C240 HSMD-C240 HSMS-C240 HSME-C240 HSMA-C240 HSML-C240 HSMC-C240

#### **Description and Extent of Change:**

The alternate manufacturing site is qualified per Broadcom's qualification process.

#### **Reasons for Change:**

Assurance of supply.

## Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change in fit, function, quality and reliability.

	Existing Manufacturing Site	Alternate Manufacturing Site
Top View		
Side View		
Bottom View		



	Existing Manufacturing Site	Alternate Manufacturing Site
Carrier Tape		
	2.00 0.05 4.00 = 0.1 4.00 = 0.1 4.00 = 0.1 1.55 = 0.05 0.81 = 0.10 0.81 = 0.10 USER FEED DIRECTION	2.00:0.05 4.00:0.1 1.00 4.00:0.1 4.00:0.1 4.00:0.1 1.00 0.78:0.10 USER FEED DIRECTION
Packaging Label	ITEM DESC: (1P)P/N: DC: 1932 LOT: Fab/Bump: COO(CN) Wafer Lot: (Q)QTY: Seal Date: 12AUG-2019 Med Exempt Nationary free Wat 1997 20C Red Exempt Nationary free Wat 1997 20C Red Exempt Nationary free Wat 1997 20C CMCLED CAT: BIN: VF: Million CAT: BIN: VF:	ITEM DESC: Laure   (1P)P/N: DC: 1932   LOT: Fab/Bump:   Vafer Lot: (Q)QTY:   Wafer Lot: (Q)QTY:   Martine Laure JULMAL   (P)Customer Item: DeptID:   CAT: BIN:   VF: IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII

#### **Effective Date of Change:**

Effective 17-December-2021, shipment may contain parts from existing or alternate manufacturing site.

#### **Qualification Data:**

Qualification data will be provided upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.