



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000813I

DATE: 01-Sep-2014

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	DS1804-050	DS1804-050+	01-Sep-2014	31-Aug-2016	Part is leaded, and a lead-free replacement exists
Lead-Free Conversion	DS3905U-020	DS3905U-020+	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS3905U-020/T&R	DS3905U-020+T&R	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331AUK	MAX9647AUK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331AUK-T	MAX9647AUK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331AXK	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331AXK-T	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331HAUK	MAX9648AUK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331HAUK-T	MAX9648AUK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331HAXK	MAX9648AXK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331HAXK-T	MAX9648AXK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339ASD	MAX9094ASD+	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339ASD-T	MAX9094ASD+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339AUD	MAX9094AUD+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339AUD-T	MAX9094AUD+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339HASD	MAX9095ASD+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339HASD-T	MAX9095ASD+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339HAUD	MAX9095AUD+	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX339HAUD-T	MAX9095AUD+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX4268EEE	N/A	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX479ESD-W	MAX4094ASD+	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX479ESD.TG002-W	MAX4094ASD+	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX6673AXK-T	MAX6673AXK+T	01-Sep-2014	31-Aug-2016	Part is leaded. Request information on lead-free version
Discontinuance	5962-8776301LA	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	5962-8865001RA	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	DS1804-100	DS1804-100+	01-Sep-2014	31-Aug-2016	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Oct-2014

Discontinuance	DS1804Z-C10+T&R	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	DS3510T+T&R	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	DS3690T+TRL	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	DS3970-E-000	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	DS3991Z+T&R/HB	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	DS3991Z+T&R/PPV	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	DS4125PW+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	DS4156PW+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AUK+C7ZW	MAX9647AUK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AUK+T10	MAX9647AUK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AUK+TGG2	MAX9647AUK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AXK+G035	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AXK+G05	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AXK+G52	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AXK+TG035	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AXK+TG05	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331AXK+TG52	MAX9647AXK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331HAUK+G002	MAX9648AUK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX331HAUK+TG002	MAX9648AUK+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	LMX339AUD+TG52	MAX9094AUD+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX1137MEUA+T	MAX1137EUA+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX15062ATA+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX274EVKIT-DIP	MAX274EVKIT-DIP+	01-Sep-2014	31-Aug-2016	EVKIT is No Longer Supported
Discontinuance	MAX31722MUA/V+	MAX31722MUA+	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX31722MUA/V+T	MAX31722MUA+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX4268EEE+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX4268EEE+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44253AUE+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44253AUE+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44254AUE+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44260ASA+	MAX44260AXT+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44260ASA+T	MAX44260AXT+T	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44262ASA+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44262ASA+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX44262AXK+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX448ACJD-2	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Oct-2014

Discontinuance	MAX478CSA+G002	MAX4092ASA+	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX478CSA+TG002	MAX4092ASA+	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX5264ACMH-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5264BCMH	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5264BCMH-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5270ACMH	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5270ACMH-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5270AEMH-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5270AEMH-T.	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5270AEMH.G044	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5661EVCMAXQU	MAX5661EVCMAXQU+	01-Sep-2014	31-Aug-2016	EVKIT is No Longer Supported
Discontinuance	MAX5839ACMH	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5839ACMH-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5839AEMH	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5839AEMH-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5839BCMH	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5839BCMH-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX5839BEMH	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAX6647YMUA+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX6647YMUA+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX9038BBEVKIT	N/A	01-Sep-2014	31-Aug-2016	EVKIT is No Longer Supported
Discontinuance	MAX9038BEBT+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX9038BEBT+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAX9687C/D	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAXQ305J-UEI+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAXQ616V-L002+T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MAXQ616V-UEI+T	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAXQ61CX-2510+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAXQ61HX-2514+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MAXQ8913EWG-T&R+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MX7537SQ/883B	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MX7537UQ/883B	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MX7548BQ+	N/A	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	MX7572AQ12	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MX7839AS	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MX7839AS-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Oct-2014

Discontinuance	MX7841AS-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	MX7841BS-T	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	REF02DSA+T	REF02CSA+	01-Sep-2014	31-Aug-2016	The part was not released
Discontinuance	REF02DSA-T	REF02CSA+	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured
Discontinuance	VSC7156YT-03	N/A	01-Sep-2014	31-Aug-2016	Part can no longer be manufactured