

Product Change Notice

PCN#: EE-PCN18001

01/03/2018

CLASSIFICATION OF CHANGE:

End of Life (EOL)

DESCRIPTION OF CHANGE:

Non-RoHS compliant ferrule fuses in AGC, ABC, MDL, MDA, GMA, GMC, GMD, C515, C517, C518, C519, C520 ferrule and axial leaded families, where there are RoHS compliant equivalent fuses available, have reached End of Life in standard, bulk and tape and reel packaging configurations.

REASON FOR CHANGE:

In pursuit of Eaton's sustainability goals and RoHS compliance commitment, non-RoHS compliant fuses where RoHS compliant alternatives exist have reached end of life status.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There are no differences in the quality, reliability, or performance between RoHS compliant and non-RoHS compliant products or any changes to form, fit, and function of these fuses.

PARTS FAMILIES AFFECTED:

Fuses in AGC, ABC, MDL, MDA, GMA, GMC, GMD, C515, C517, C518, C519 and C520 families are affected by this change. Please see attached excel file for detailed list of catalog numbers, RoHS compliant catalog numbers and corresponding UPCs. Any inventory of existing product is saleable and should not be returned.

TIME SCHEDULE:

Last Time Buy Date: February 28, 2018

Last Time Shipment Date: May 31, 2018

SAMPLE AVAILABILITY:

Available upon request

QUALIFICATION DATA:

Available upon request

ISSUED BY:

Nick Stone

Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#) and see Eaton's Electronics division website for more information on RoHS compliance.