

Issue date: January 30, 2019

PTN No.:1018009

Shunichi Kawashima  
Manager  
ATP Div.  
LSI Production control Dept.  
ROHM Co., Ltd.

## Notification of Product Discontinuance

Dear Valued Customer

This letter intends as a formal notification that ROHM Co., Ltd. is discontinuing the production of the following product. We acknowledges the obligation to promptly inform our customers of the intent to exit products to enable out customers the ability to prepare for alternatives and/or assist in our product portfolio renewal process.

It would be very appreciated if you could your reply by March 29, 2019

If ROHM does not receive acknowledgment by March 29, 2019,  
it will be assumed that this change is acceptable.

Your early reply in this regard would be very much appreciated.

Product category	Affected part number(s)	Suggested replacement product
IC	Please refer to the attached.	
<u>Reason for discontinuance</u>  Due to aging plant and equipment for production, Rohm is unable to sustain manufacturing.		
<u>Product discontinuance date</u>  September 29, 2019		
<u>Order after discontinuance</u> If you need discontinue item after termination, please inform us the quantity untill March 29, 2019 We will produce the discontinue item you need. However all of the quantity you need will be supplied at one time.		
<b>Last Time Buy: 3/29/2019</b> <b>Last Time Ship: 9/29/2019</b>		

RGTSZ22304·04·001

EOL PN	Recommended Alt PN
BA12003BF-E2	BA12003DF-ZE2
BA12004BF-E2	BA12004DF-ZE2
BA10324A	LM324F-E2
BA10339	LM339F-E2
BU4001B	none
BU4011B	none
BU4030B	BU4030BF-BZE2
BU4066BC	BU4066BCF-BZE2
BU4069UB	none
BU4070B	none
BU4081B	none
BU4093B	none
BU4584B	none
BA12003B	BA12003DF-ZE2
BA823	none
BD9428	BD9428EFV-E2
BU2090	BU2090F-E2
BU4015B	none
BU4028B	none
BU4051BC	BU4051BCF-BZE2
BU4052BC	BU4052BCF-BZE2
BU4053BC	none
BU4094BC	BU4094BCF-BZE2
BU4538B	none
BU4551B	BU4551BF-BZE2
BA682A	none
BA829	none
BA10358	LM358F-E2
BA10393	LM393F-E2
BA3121	BA3121F-E2
BA4558	BA4558F-BZE2
BA4560	BA4560F-BZE2
BR24G01-3	BR24T16-WZ
BR24G01-3A	BR24T16-WZ
BR24G02-3	BR24T16-WZ
BR24G02-3A	BR24T16-WZ
BR24G04-3	BR24T16-WZ
BR24G08-3	BR24T16-WZ
BR24G08-3A	BR24T16-WZ
BR24G128-3	BR24T128-WZ
BR24G16-3	BR24T16-WZ
BR24G1M-3A	BR24G1MF-3AGTE2
BR24G256-3	BR24T256-WZ
BR24G256-3A	BR24T256-WZ
BR24G32-3	BR24T64-WZ

BR24G32-3A	BR24T64-WZ
BR24G512-3A	BR24G512FJ-3AGTE2
BR24G64-3	BR24T64-WZ
BR24G64-3A	BR24T64-WZ
BR24L01A-W	BR24T16-WZ
BR24L02-W	BR24T16-WZ
BR24L08-W	BR24T16-WZ
BR24L16-W	BR24T16-WZ
BR24L64-W	BR24T64-WZ
BR24T02-W	BR24T16-WZ
BR24T08-W	BR24T16-WZ
BR24T128-W	BR24T128-WZ
BR24T16-W	BR24T16-WZ
BR24T256-W	BR24T256-WZ
BR24T256-WVP	BR24T256-WZ
BR24T32-W	BR24T64-WZ
BR24T64-W	BR24T64-WZ
BR25G256-3	BR25G256F-3GE2
BR25L160-W	BR25L160FJ-WE2
BR25L320-W	BR25G320FJ E2
BR93G46-3A	BR93G46FJ-3AGTE2
BR93G56-3A	BR93G56FJ-3AGTE2
BR93G86-3	BR93G86FJ-3GTE2
BR93G86-3A	BR93G86FJ-3AGTE2
BR93L46-W	BR93G46FJ-3AGE2
BR93L56-W	BR93G56FJ-3AGTE2
BR93L66-W	BR93G66FJ-3AGTE2
BR93L86-W	BR93G86FJ-3AGTE2
BU8874	none
BA6219B	BA6219BFP-YE2
BA6222	none
BA6238A	none
BA6247	BA6247FP-YE2
BA5417	none
BA6209N	none
BA6238AN	none
BA6286N	none
BA7615N	none
BA7615N-BZ	none
BA6161N	BA6161F-BZE2
BA10358N	LM358F-E2
BA10393N	LM393F-E2
BA3121N	BA3121F-BZE2
BA4558N	BA4558F-BZE2
BA4560N	BA4560F-BZE2
BA4560N-BZ	BA4560F-BZE2

BA7612N	none
BD95820N-LB	BD95820F-LBE2
BD9582N	BD95820F-LBE2
BA6218	none
BA6283N	none
BA6418N	none
BA6956AN	none
BA5406	none
BA5415A	none
BA3823LS	none
BA3823LS-BZ	none
BA7230LS	none