SHARP S12MD1V/S12MD3

S12MD1V/S12MD3

Photothyristor Coupler

* Lead forming type (I type) and taping reel type (P type) of \$12MD1V are also available. (\$12MD1VI/\$12MDIP)

■ Features

1. High RMS ON-state current (I_T : MAX. $200 mA_{rms}$)

2. High repetitive peak OFF-state voltage (VDRM: MIN. 400V)

3. Trigger current I $_{FT}$: MAX. 15mA at R $_{G}$ = $20k\Omega$

4. For half-wave control ••• \$12MD1V For full-wave control ••• \$12MD3


5. Recognized by UL, file No. E64380

* S12MD1V and S12MD3 are for 100V line

■ Applications

- 1. ON-OFF operation for a low power load
- 2. For triggering high power thyristor and triac

■ Outline Dimensions (Unit: mm)



■ Absolute Maximum Ratings

 $(Ta = 25^{\circ}C)$

Parameter		C11	Rating		Unit	
		Symbol	S12MD1V	S12MD3	Unit	
Input	Forward current	I_F	50		mA	
	Reverse voltage	V_R	6		V	
Output	RMS ON-state current	I_T	200		mA _{rms}	
	*1 Peak one cycle surge current	Isurge	2		A	
	*2 Repetitive peak OFF-state voltage	V_{DRM}	400		V	
	*2 Repetitive peak reverse voltage	V _{RRM}	400	-	V	
*3 Isolation voltage		V_{iso}	5 000	1 500	V_{rms}	
Operating temperature		T opr	- 30 to + 100		°C	
Storage temperature		T stg	- 40 to + 125		°C	
*4 Soldering temperature		T sol	260		°C	

^{*1 50}Hz, sine wave

■ Electro-optical Characteristics

 $(Ta = 25^{\circ}C)$

Parameter		Symbol	Conditions	MIN.	TYP.	MAX.	Unit
Input	Forward voltage	$V_{\rm F}$	$I_F=30mA$	-	1.2	1.4	V
	Reverse current	I_R	$V_R = 3V$	-	-	10-5	A
Output	Repetitive peak OFF-state current	I_{DRM}	$V_{DRM} = Rated, R_G = 20k\Omega$	-	-	10-6	A
	*5Repetitive peak reverse current	I_{RRM}	$V_{RRM} = Rated, R_G = 20k\Omega$	-	-	10-6	A
	ON-state voltage	V_{T}	$I_T = 200 mA$	-	1.0	1.4	V
	Holding current	I_{H}	$V_D = 6V$, $R_G = 20k\Omega$	-	0.3	1	mA
	Critical rate of rise of OFF-state voltage	dV/dt	$V_{DRM} = 1/\sqrt{2}$ Rated, $R_G = 20k\Omega$	3	-	-	V/µs
Transfer- charac- teristics	Minimum trigger current	IFT	$V_D\!=6V,R_L\!=100\Omega$, $R_G\!=20k\Omega$	-	-	15	mA
	Isolation resistance	R _{ISO}	DC500V, 40 to 60% RH	5 x 10 ¹⁰	1011	-	Ω
	Turn-on time	t _{on}	$\begin{split} V_D &= 6V, I_F = 30 \text{mA}, R_G = 20 \text{k}\Omega , \\ R_L &= 100 \Omega \end{split}$	-	10	60	μs

^{*5} Applies only to **S12MD1V**

Fig. 1 RMS ON-state Current vs.
Ambient Temperature





Fig. 2 Forward Current vs.



^{*3 40} to 60% RH, AC for 1 minute

 $^{*2} R_G = 20k\Omega$

^{*4} For 10 seconds

Fig. 3 Forward Current vs. Forward Voltage




Fig. 5 Minimum Trigger Current vs.
Gate Resistance




Fig. 7 Critical Rate of Rise of OFF-state Voltage vs. Ambient Temperature




Fig. 4 Minimum Trigger Current vs.
Ambient Temperature




Fig. 6 Break Over Voltage vs. Ambient Temperature




Fig. 8 Holding Current vs.

Ambient Temperature






Fig. 9 Repetitive Peak OFF-state Current vs. Ambient Temperature




■ Basic Operation Circuit

● S12MD1V

Medium/High Power Thyristor Drive Circuit




Medium/High Power Triac Drive Circuit (Zero-cross Operation)






● S12MD3

Low Power Load Drive Circuit



Medium/High Power Triac Drive Circuit



 \bullet Please refer to the chapter "Precautions for Use" (Page 78 to 93).

NOTICE

- •The circuit application examples in this publication are provided to explain representative applications of SHARP devices and are not intended to guarantee any circuit design or license any intellectual property rights. SHARP takes no responsibility for any problems related to any intellectual property right of a third party resulting from the use of SHARP's devices.
- •Contact SHARP in order to obtain the latest device specification sheets before using any SHARP device. SHARP reserves the right to make changes in the specifications, characteristics, data, materials, structure, and other contents described herein at any time without notice in order to improve design or reliability. Manufacturing locations are also subject to change without notice.
- Observe the following points when using any devices in this publication. SHARP takes no responsibility for damage caused by improper use of the devices which does not meet the conditions and absolute maximum ratings to be used specified in the relevant specification sheet nor meet the following conditions:
 - (i) The devices in this publication are designed for use in general electronic equipment designs such as:
 - Personal computers
 - Office automation equipment
 - Telecommunication equipment [terminal]
 - Test and measurement equipment
 - Industrial control
 - Audio visual equipment
 - Consumer electronics
 - (ii) Measures such as fail-safe function and redundant design should be taken to ensure reliability and safety when SHARP devices are used for or in connection with equipment that requires higher reliability such as:
 - Transportation control and safety equipment (i.e., aircraft, trains, automobiles, etc.)
 - Traffic signals
 - Gas leakage sensor breakers
 - Alarm equipment
 - Various safety devices, etc.
 - (iii) SHARP devices shall not be used for or in connection with equipment that requires an extremely high level of reliability and safety such as:
 - Space applications
 - Telecommunication equipment [trunk lines]
 - Nuclear power control equipment
 - Medical and other life support equipment (e.g., scuba).
- •Contact a SHARP representative in advance when intending to use SHARP devices for any "specific" applications other than those recommended by SHARP or when it is unclear which category mentioned above controls the intended use.
- •If the SHARP devices listed in this publication fall within the scope of strategic products described in the Foreign Exchange and Foreign Trade Control Law of Japan, it is necessary to obtain approval to export such SHARP devices.
- •This publication is the proprietary product of SHARP and is copyrighted, with all rights reserved. Under the copyright laws, no part of this publication may be reproduced or transmitted in any form or by any means, electronic or mechanical, for any purpose, in whole or in part, without the express written permission of SHARP. Express written permission is also required before any use of this publication may be made by a third party.
- Contact and consult with a SHARP representative if there are any questions about the contents of this
 publication.