## **PRODUCT DISCONTINUANCE NOTICE#** CQ-14-04

ISSUE DATE: April 25, 2014

LAST BUY DATE: April 25, 2015

LAST SHIP DATE: July 25, 2015

## REASON FOR DISCONTINUANCE:

A manufacturing related issue requires us to discontinue these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at <a href="www.IDT.com">www.IDT.com</a> or the marketing contact listed below:

Paul Barton 408-284-8306

MIP <u>paul.barton@idt.com</u>

TCS <u>clocks@idt.com</u>

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group	Remark
275GI-13LF	None	None	N/A	TCS	
275GI-13LFT	None	None	N/A	TCS	
CSP2510CPGG	None	2510CGLF	Available Now	MIP	
CSP2510CPGG8	None	2510CGLFT	Available Now	MIP	