

## **Bulletin #1607271**

## **User Registration**

Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, "how-to" and design documents, product change notices (PCN) and other valuable content available only to registered users. <a href="http://www.silabs.com/profile">http://www.silabs.com/profile</a>

Bulletin Date: 7/27/2016	Bulletin Effective Date: 7/27/2016
Title: Si7050/1/3/4/5 Data Sheet update from rev 1.13 to rev 1.14	
Bulletin Details	
Description: The Si7050/1/3/4/5 data sheet was updated from Revision 1.13 to Revision 1.14. The following changes were made:  ☐ Updated "No Hold Master Mode" diagram in "5.1. Issuing a Measurement Command" on page 13.  ☐ Updated diagram in "5.4. Firmware Revision" on page 16.  ☐ Updated notes in Table 14, "PCB Land Pattern Dimensions," on page 21 to remove unnecessary recommendation about a need for no clean solder paste.	
Reason: Correcting minor errors found in data sheet.	
Product Identification: Si7050-A20-IM, Si7050-A20-IMR Si7051-A20-IM, Si7051-A20-IMR Si7053-A20-IM, Si7053-A20-IMR Si7054-A20-IM, Si7054-A20-IMR Si7055-A20-IM, Si7055-A20-IMR Si7055-A20-ZM, Si7055-A20-ZMR	
This change is considered a minor change which does not affect form, fit, function, quality, or reliability. The information is being provided as a customer courtesy.  Please contact your local Silicon Labs sales representative with any questions about this notification. A list of Silicon Labs sales representatives may be found at <a href="https://www.silabs.com">www.silabs.com</a>	