



Product Change Notification

PCN No: MULTI-18-0208-CCB-0451

New sealing tape from PSA to HSA type

Notification Date: 05/18/2018

Qualification Data Availability Date: 02/23/2018

Notification Period: 30 days

Sample Availability Date: Not Applicable

Proposed First Ship Date for Change: 06/17/2018

Last Date of Manufacture of Unchanged Product: 10/26/2018

Dear Valued Skyworks Customer:

Please be advised that Skyworks Solutions Inc. is introducing the following product change(s):

Description and Scope of Change

New Sealing tape is proposed in order to avoid quality Issues in Customers' SMT processes

Products Affected

SKY65116-21; SKY65141-31; SKY65141-41; SKY65142-21; SKY65145-21; SKY65145-31; SKY65160-11; SKY65187-11; SKY65192-11; SKY65225-12; SKY65312-11; SKY65312-31; SKY65342-11; SKY65342-31; SKY65345-11; SKY65350-11; SKY65350-21; SKY65350-25; SKY65351-11; SKY65351-21; SKY65351-25; SKY65385-11; SKY65386-11; SKY65387-11; SKY65388-11; SKY73305-11; SKY73306-21; SKY73307-31; SKY78010-12; SKY78011-21; SKY78013-11; SKY78030-18

Method for Identifying Changed Product

Full product change traceability is maintained by: date code

Reason for Change

As part of Skyworks continuous quality improvement program we are changing the tape and Reel cover tape. The current PSA Cover Tape has activated glue that in some cases could leave residues on Jigs, potentially triggering jamming and causing units to be thrown from carrier tape pocket. In order to avoid this situation, HSA sealing tape is proposed as it is heat activated, and leaves no glue residues on SMT tooling.

Anticipated Impact on Form, Fit Function, Reliability, Quality or Safety

No customer impact is anticipated with this change; there is no change to form, fit, function, reliability, quality or safety.

Qualification Plan Summary

Qualification not required; no change made to part

Launch Plan

Implement upon customer approval. May consume existing material.

Please contact your Skyworks customer service representative with any questions or comments regarding this change. If you are unsure whom to contact, please email Skyworks Change Management at Skyworks.CCB@Skyworksinc.com.

Skyworks Solutions, Inc.

20 Sylvan Road, Woburn, MA 01801

USA: (781) 376-3000 • Asia: 886 2 2735 0399

Europe: 33 (0)1 43548540 • Fax: (781) 376-3300

On the Web: www.skyworksinc.com