



Product Discontinuation

PDN-ION-785-2017

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ION - I/O and Networks	DNC	Product Discontinuation	Notify Distributors and Field	8/9/2017

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

This notice is to inform you that Phoenix Contact will be discontinuing the SUBCON 37L/F-SH, number 5604027. The reason for discontinuation is end of life of the product.					
	be the SUBCON 37/F-SH number 2300986. The difference between lease see pictures for additional details.	these two			
Stock Status					
Can existing stock still be used?	Yes				

Transaction Dates			
Last Buy from Phoenix Contact:	1/31/2018		
Last Scheduled Ship from Phoenix Contact:	1/31/2018		





Product Discontinuation







Product Discontinuation

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info: Andres Suazo Wildt asuazo@phoenixcon.com

Thank you,

h he

Ira Sharp

Product Marketing Manager, I/O and Network





Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
5604027	SUBCON 37L/F-SH	2300986	SUBCON 37/F-SH