



Product Change Notification - KSRA-04DSQL228

Date:

09 Mar 2020

Product Category:

Ethernet Controllers

Affected CPNs:**Notification subject:**

Memo # ML0320200017: End of Life (EOL) of LAN91C93I-MU catalog part number (CPN)

Notification text:**PCN Status:**

End of Life (EOL) notification

Microchip Parts Affected:

Please open one of the icons found in the Affected CPNs section above.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field below labeled as PCN_#_Affected_CPN.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:

The LAN91C93I-MU catalog part number (CPN) will be moving to End of Life (EOL) status effective today. This catalog part number will no longer be offered after August 16, 2020. Please review the attached parts affected list below for details about replacement parts if applicable.

If replacement parts are not listed in the attached list, please contact your [Local Sales Representative](#).

Reason for EOL:

No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates:

Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

Last date for bookings (LTB): June 16, 2020

Last date for shipments (LTS): August 16, 2020

Revision History:

March 07, 2020: Issued the EOL notification.

Attachment(s):

[PCN_KSRA-04DSQL228_Affected_CPN.pdf](#)

[PCN_KSRA-04DSQL228_Affected_CPN.xls](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select



login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

LAN91C93I-MU