



Product Change Notification / SYST-27BQXY881

Date:

28-Jan-2015

Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

PCN Type:

Document Change

Notification Subject:

ERRATA - dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 Family Silicon Errata and Data Sheet Clarification Errata Document Revision

Affected CPNs:

[SYST-27BQXY881_Affected_CPN_01282015.pdf](#)
[SYST-27BQXY881_Affected_CPN_01282015.csv](#)

Notification Text:

SYST-27BQXY881

Microchip has released a new DeviceDoc for the dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 Sil Err and DS Cla of devices. If you are using one of these devices please read the document located at [dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 Sil Err and DS Cla](#).

Notification Status: Final

Description of Change: Added new silicon issue 34 (I2C).

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 28 Jan 2015

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 Sil Err and DS Cla](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."