

Structure	Silicon Monolithic Integrated Circuit
Product series	PWM Driver for combi drive
Туре	BD7790KVT
Function	<ul> <li>3-phase-sensor-less system, therefore don't need three hall sensors for spindle motor driver.</li> </ul>

• Stability high-speed start from the state of the stop for spindle motor driver.

### OAbsolute maximum ratings

Parameter	Symbol	Limits	Unit
Power MOS supply voltage	PVcc	6	V
Control circuit power supply voltage	Vcc	6	V
Maximum driver output current	IoMAX	3 #1	А
Power dissipation	Pd	1.37 #2	W
Operating temperature range	Topr	-30~85	°C
Storage temperature range	Tstg	-55~150	°C
Joint part temperature	Tjmax	150	°C

#1 The current is guaranteed 3.0A in case of the current is turned on/off in a duty-ratio of less than 1/10 with a maximum on-time of 5ms and when short brake.

#2 PCB (70mm × 70mm × 1.6mm,occupied copper foil is less than 3%,glass epoxy standard board) mounting. Reduce power by 11.0mW for each degree above 25°C.

## ORecommended operating conditions(Ta=-30~+85°C)

[Set the power supply voltage taking allowable dissipation into considering]

Parameter	Symbol	MIN	TYP	MAX	Unit
Power MOS supply voltage	PVcc	4.0	5.0	5.5	V
Control circuit power supply voltage	Vcc	4.0	5.0	5.5	V

This product isn't designed for protection against radioactive rays.



#### O Electrical characteristics

(Unless otherwise noted Ta=25°C, Vcc=PVcc=5V, Vref=1.25V, RL(ACT,STP,LOAD)=8Ω+47 μ H, RL(SP)=2Ω+47 μ H, RNF=0.2Ω, CTL1,2=3.3V, GVSW=0V, VIN1,2,3,4,5,6=OPEN, VCOM=OPEN, VCCOM=OPEN, VCOUT=OPEN)

	Parameter	Symbol	MIN.	TYP.	MAX.	Unit	N, VCCOM=OPEN, VCOUT=OPE
Circuit current	Quiescent current	ICC	-	8	20	mA	CTL1,2=H
	Current in standby mode	IST	—	_	0.2	mA	CTL1,2=L
	Input dead zone (one side)	VDZACT1,2,3	-	-	3	mV	
Actuator driver	Output offset voltage	VOO1,2,3	-50	-	50	mV	
block	Voltage gain (CH1,2,3)	GVC1,2,3	15.5	17.5	19.5	dB	External input resistor 10kΩ
DIOCK	Output On resistor (top and bottom)	RON1,2,3		1.2	1.8	Ω	lo=500mA
	PWM frequency	f1,2,3CH	215	310	405	kHz	
	Input dead zone (one side)	VDZ4,5	10	30	50	mV	
Otopping driver	Output offset voltage	VOO4,5	-50	—	50	mV	
Stepping driver block	Voltage gain	GVC4,5	15.5	17.5	19.5	dB	
DIOCK	Output On resistor (top and bottom)	RON4,5		1.6	2.4	Ω	lo=500mA
	PWM frequency	f4,5CH	215	310	405	kHz	
	Input dead zone (one side)	VDZ6	20	60	100	mV	CTL1=H, CTL2=L
المحمانية مراين بمر	Output offset voltage	VOO6	-50	_	50	mV	CTL1=H, CTL2=L
Loading driver block	Voltage gain	GVC6	15.5	17.5	19.5	dB	CTL1=H, CTL2=L
DIOCK	Output On resistor (top and bottom)	RON6	—	1.8	2.7	Ω	lo=500mA, CTL1=H, CTL2=L
	PWM frequency	f6CH	215	310	405	kHz	CTL1=H, CTL2=L
	Input dead zone of gm1(one side)	VDZSP1	2	30	100	mV	
	Input dead zone of gm2(one side)	VDZSP2	6	90	300	mV	GVSW=M
	Input dead zone of gm3(one side)	VDZSP3	10	150	500	mV	GVSW=H
Carica alla administra	Input output gain 1	gm1	0.88	1.1	1.32	A/V	
Spindle driver block	Input output gain 2	gm2	0.28	0.36	0.44	A/V	GVSW=M
DIOCK	Input output gain 3	gm3	0.17	0.22	0.27	A/V	GVSW=H
	Output On resistor (top and bottom)	RONSP	—	0.6	1.4	Ω	lo=500mA
	Output limit voltage	VLIMSP	0.18	0.22	0.26	V	
	PWM frequency	fSP	—	167	_	kHz	
	Vref drop mute ON threshold voltage	VMVref	—	0.7	1.0	V	
	Vcc drop mute ON threshold voltage	VMVccD	3.2	3.6	4.0	V	
	CTL1 L voltage	VCTL1L	0	—	1.0	V	
Others	CTL1 H voltage	VCTL1H	2.0	—	3.3	V	
	CTL2, GVSW L voltage	VCTL2L, VGVL	0	—	1.0	V	
	CTL2, GVSW M(Hi-z) voltage	VCTL2M, VGVM	1.6	—	2.0	V	OPEN (Hi-z) is also available
	CTL2, GVSW H voltage	VCTL2H, VGVH	2.6	-	3.3	V	
GVSW	L M (Hi-z)	Н					
Gain mode	gm1 gm2	gm3					

		<u> </u>	<u> </u>			
CTL1	CTL2	Brake mode	SPINDLE Output	CH1,2,3 Output	CH4,5 Output	CH6 Output
	L	_	Hi-Z	Hi-Z	Hi-Z	Hi-Z
L	М	Short brake	ACTIVE	Hi-Z	Hi-Z	Hi-Z
	Н	Short blake	ACTIVE	ACTIVE	ACTIVE	Hi-Z
	L		Hi-Z	Hi-Z	ACTIVE	ACTIVE
Н	M (Hi-z)	Reverse brake	ACTIVE	Hi-Z	Hi-Z	Hi-Z
	H		ACTIVE	ACTIVE	ACTIVE	Hi-Z

Please supply the middle level voltage for CTL2 when using it in the mode of CTL1=L and CTL2=M.

OPackage outlines







## OBlock diagram / Application circuit



#### O PIN DESCRIPTION

Pin No.	Symbol	Description	Pin No.	Symbol	Description
1	IN6	PWM Driver (CH6) input	25	U	Spindle driver output U
2	VO6F	PWM Driver(CH6) positive output	26	V	Spindle driver output V
3	VO6R	PWM Driver(CH6) negative output	27	PVcc22	Spindle driver power supply22
4	CTL1	Driver logic control input1	28	RNF2	Spindle driver current sense output2
5	CTL2	Driver logic control input2	29	W	Spindle driver output W
6	VO1F	PWM Driver(CH1) positive output	30	PGND3	PWM driver power ground3
7	VO1R	PWM Driver(CH1) negative output	31	VO4F	PWM Driver(CH4) positive output
8	PGND1	PWM driver power ground1	32	VO4R	PWM Driver(CH4) negative output
9	VO2F	PWM Driver(CH2) positive output	33	PVcc3	PWM driver power supply3
10	VO2R	PWM Driver(CH2) negative output	34	VO5F	PWM Driver(CH5) positive output
11	PVcc1	PWM driver power supply1	35	VO5R	PWM Driver(CH5) negative output
12	VO3F	PWM Driver(CH3) positive output	36	Vref	Reference voltage input
13	VO3R	PWM Driver(CH3) negative output	37	CNF5	PWM driver (CH5) feedback filter
14	TEST1	Test terminal1	38	CNF4	PWM driver (CH4) feedback filter
15	TEST2	Test terminal2	39	CNF3	PWM driver (CH3) feedback filter
16	TEST3	Test terminal3	40	CNF2	PWM driver (CH2) feedback filter
17	GND	Pre unit ground	41	CNF1	PWM driver (CH1) feedback filter
18	Vcc	Pre unit power supply	42	IN1	PWM driver (CH1) input
19	COUT	Smoothing capacitor connection terminal(Output side)	43	IN2	PWM driver (CH2) input
20	CCOM	Smoothing capacitor connection terminal(COM side)	44	IN3	PWM driver (CH3) input
21	COM	Motor coil center point input terminal	45	IN4	PWM driver (CH4) input
22	GVSW	Control for gain of spindle	46	IN5	PWM driver (CH5) input
23	PVcc21	Spindle driver power supply21	47	INSP	Spindle driver input
24	RNF1	Spindle driver current sense output1	48	FG	Frequency generator output

Positive/Negative of the output terminals are determined in reference to those of the input terminals.



### Cautions on use

1. Absolute maximum ratings

This IC might be destroyed when the absolute maximum ratings, such as impressed voltage (PVcc, Vcc) or the operating temperature range (Topr), is exceeded, and whether the destruction is short circuit mode or open circuit mode cannot be specified. Please take into consideration the physical countermeasures for safety, such as fusing, if a particular mode that exceeds the absolute maximum rating is assumed. 2. Reverse polarity connection

- Connecting the power line to the IC in reverse polarity (from that recommended) will damage the part. Please utilize the direction protection device as a diode in the supply line.
- 3. GND line
- The ground line is where the lowest potential and transient voltages are connected to the IC.
- 4. Thermal design
  - Do not exceed the power dissipation (Pd) of the package specification rating under actual operation, and please design enough temperature margins.
- 5. Short circuit mode between terminals and wrong mounting
  - Do not mount the IC in the wrong direction and be careful about the reverse-connection of the power connector.

Moreover, this IC might be destroyed when the dust short the terminals between them or GND.

- 6. Radiation
  - Strong electromagnetic radiation can cause operation failures.
- 7. ASO (Area of Safety Operation)
  - When using the IC, set the output transistor so that it does not exceed absolute maximum ratings or ASO.
- 8. TSD (Thermal Shut-Down)

The TSD is activated when the junction temperature (Tj) reaches 175<sup>o</sup>C (with +/-25<sup>o</sup>C hysteresis), and the output terminal is switched to Hi-z. The TSD circuit designed to shut the IC off to prevent runaway thermal operation. It is not designed to protect or guarantee its operation. Do not continue to use the IC after operating this circuit.

9. Vcc, GND and RNF wiring layout

Vcc, GND and RNF layout should be as wide as possible and at minimum distance. Wire to ground to prevent Vcc-PVcc and GND-PGND-GND side of RNF resistor from having common impedance. Connect a capacitor between Vcc and GND to stabilize.

10. Regarding input pin of the IC

This monolithic IC contains P+ isolation and P substrate layers between adjacent elements to keep them isolated. PN junctions are formed at the intersection of these P layers with the N layers of other elements, creating a parasitic diode or transistor. For example, the relation between each potential is as follows:

When GND > Pin A and GND > Pin B, the PN junction operates as a parasitic diode.

When Pin B > GND > Pin A, the PN junction operates as a parasitic transistor.

Parasitic diodes can occur inevitably in the structure of the IC. The operation of parasitic diodes can result in mutual interference among circuits, operational faults, or physical damage. Accordingly, methods by which parasitic diodes operate, such as applying a voltage that is lower than the GND (P substrate) voltage to an input pin, should not be used.





11. Capacitor between Vcc and GND

This IC has steep change of the voltage and current because of PWM driver. Therefore, the capacitor controls Vcc voltage by attaching a capacitor between Vcc and GND. Wiring impedance decreases the capacitors capabilities if the capacitor is far from the IC. Therefore, a capacitor should be placed between Vcc and GND, close to the IC.

12. Supply fault, ground fault and short-circuit between output terminals

Do not short-circuit between any output terminal and supply terminal (supply fault) or ground (ground fault), or between any output terminals (load short-circuit). When mounting the IC on the circuit board, be extremely cautious about the orientation of the IC. If the orientation is mistaken, the IC may break down and produce smoke in some cases.

13. Inspection by the set circuit board

When testing the IC on an application board, connecting a capacitor to a pin with low impedance subjects the IC to stress. Always discharge capacitors after each process or step. Always turn the IC's power supply off before connecting it to, or removing it from a jig or fixture, during the inspection process. Ground the IC during assembly steps as an antistatic measure. Use similar precaution when transporting and storing the IC.

## 14. Reverse-rotation braking

High-speed rotation may cause reverse-rotation braking. Monitor the voltage applied to the output terminal and consider the revolutions applied to the reversed-rotation brake.

15. Application circuit

It is one sample that explains standard operation and usage of this IC about the described example of the application circuit and information on the constant etc. Therefore, please be sure to consult with our sales representative in advance before mass production design, when a circuit different from application circuit is composed of external.

	Notes
	or reproduction of this document, in part or in whole, is permitted without the ROHM Co.,Ltd.
The content	specified herein is subject to change for improvement without notice.
"Products").	specified herein is for the purpose of introducing ROHM's products (hereinafte If you wish to use any such Product, please be sure to refer to the specifications e obtained from ROHM upon request.
illustrate the	application circuits, circuit constants and any other information contained hereir standard usage and operations of the Products. The peripheral conditions mus account when designing circuits for mass production.
However, sh	vas taken in ensuring the accuracy of the information specified in this document nould you incur any damage arising from any inaccuracy or misprint of such ROHM shall bear no responsibility for such damage.
examples or implicitly, an other parties	al information specified herein is intended only to show the typical functions of and f application circuits for the Products. ROHM does not grant you, explicitly o y license to use or exercise intellectual property or other rights held by ROHM and s. ROHM shall bear no responsibility whatsoever for any dispute arising from the technical information.
equipment c	es specified in this document are intended to be used with general-use electronic or devices (such as audio visual equipment, office-automation equipment, commu- ices, electronic appliances and amusement devices).
The Product	s specified in this document are not designed to be radiation tolerant.
	A always makes efforts to enhance the quality and reliability of its Products, a a fail or malfunction for a variety of reasons.
against the failure of any shall bear n	ure to implement in your equipment using the Products safety measures to guard possibility of physical injury, fire or any other damage caused in the event of the y Product, such as derating, redundancy, fire control and fail-safe designs. ROHM o responsibility whatsoever for your use of any Product outside of the prescribed t in accordance with the instruction manual.
system whic may result in instrument, controller or of the Produ	ts are not designed or manufactured to be used with any equipment, device or the requires an extremely high level of reliability the failure or malfunction of which in a direct threat to human life or create a risk of human injury (such as a medica transportation equipment, aerospace machinery, nuclear-reactor controller, fuel- other safety device). ROHM shall bear no responsibility in any way for use of any ucts for the above special purposes. If a Product is intended to be used for any I purpose, please contact a ROHM sales representative before purchasing.
be controlle	I to export or ship overseas any Product or technology specified herein that may d under the Foreign Exchange and the Foreign Trade Law, you will be required to nse or permit under the Law.



Thank you for your accessing to ROHM product informations. More detail product informations and catalogs are available, please contact us.

# ROHM Customer Support System

http://www.rohm.com/contact/