

PRODUCT CHANGE NOTIFICATION FIBER DISTRIBUTION 20200924-1 **Product Category CONNECTIVITY & PATHWAYS Product Group** 24-Sep-20 ISSUE DATE: **IMPACTED REGIONS:** ✓ NA ✓ EMEA ✓ LATAM ✓ AP OTHER **DESCRIPTION OF CHANGE: (Required)** We transitioned from Ph Br to Zirconia split sleeves, E-2000 connector to be obsoleted without replacement parts. Photos/Drawing (where applicable) IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable) Reference Page 2 / Linked PDF DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY: Year Month Day SCHEDULE FOR CHANGE (YYYY) (MM) (DD)

New product sample availability date

Old product discontinuation date*

*Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months are

^{*}Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part Numbers	Replacement Part 1
FD1W6EIDSC	No-Replacement
FD1W12EIDSC	No-Replacement
FD1W12BLDLC	No-Replacement
FD1W12EIDLC	No-Replacement
FD1W24BLDLC	No-Replacement
FD1W24EIDLC	No-Replacement
FD1W24EIDSC	No-Replacement
FD1W6BLDSC	No-Replacement
FD1W12BLDSC	No-Replacement
FD1W12BUDE2KZ	No-Replacement
FD1W24BUDE2KZ	No-Replacement
FAPH6WBUDE2KZ	No-Replacement
CMMJBL	No-Replacement
CMMJEI	No-Replacement
CMDBUSCEI-C/N	No-Replacement
CMDCLSCBL	No-Replacement
CMDEISCGR/N	No-Replacement
CMDEISCOR/N	No-Replacement
CMDEISCRD/N	No-Replacement
FC12SCMSAMPLE	No-Replacement
FC26N-06-03AF	No-Replacement
FC26N-06-03AS	No-Replacement
FC26N-12-03AF	No-Replacement
FC26N-12-03AS	No-Replacement
FC26N-12-3SAS	No-Replacement
FCE1U24MMSC/N	No-Replacement
FCE1U46BLSC/N	No-Replacement
FCE4U124BLDSC/N	No-Replacement
FCE4U48BLDSC/N	No-Replacement
FLBE2WBUDSC	No-Replacement
FLBE3WBUDSC	No-Replacement
FT1W12DSC	No-Replacement