

Product Change Notification - LIAL-01RFYA098

Date:

21 Mar 2018

Product Category:

Clock and Timing - Oscillators; Others; Clock and Timing - Clock Generation; Clock and Timing - Clock and Data Distribution

Affected CPNs:

Notification subject:

End of Life (EOL) of PL130, PL502, PL520, PL580, PL602-00/03/04/11/3x, PL620 and PL680 Micrel device families

Notification text:

PCN Status:

End of Life (EOL) notification

Microchip Parts Affected:

Please open the attachments found in the attachments field below labeled as

PCN_#_Affected_CPN.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:

The PL130, PL502, PL520, PL580, PL602-00/03/04/11/3x, PL620 and PL680 Micrel device families will be moving to End of Life (EOL) status effective today. These device families will no longer be offered after December 31, 2018. Please review the attached parts affected list for details about replacement parts if applicable.

Reason for EOL:

No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates:

Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows: Last date for bookings (LTB): June 15, 2018

Last date for shipments (LTS): December 31, 2018

Revision History:

March 02, 2018: Issued the EOL notification.

March 21, 2018: Revised this EOL notification to be issued to all affected customers.

Attachment(s):

PCN_LIAL-01RFYA098_Affected_CPN.pdf PCN_LIAL-01RFYA098_Affected_CPN.xlsx

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP



home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchip DIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

LIAL-01RFYA098 - End of Life (EOL) of PL130, PL502, PL520, PL580, PL602-00/03/04/11/3x, PL620 and PL680 Micrel device families

Affected Catalog Part Numbers (CPN)

PL502-00DC PL502-01SC-R PL502-02SC-R PL502-03SC-R PL502-30DC PL502-30WC PL502-35OC PL502-35OI PL502-37OC PL502-37OC-R PL502-38OC PL502-39OI PL502-39OI-R PL502-39UQC-R PL520-00DC PL520-08OC PL520-08OC-R PL520-20DC PL520-30DC PL520-80DC PL580-30DC PL580-37OC PL580-39OI PL602-00DC PL602-03SC-R PL602-04SC PL602-11OC PL602-37OC-R PL602-37QC-R PL602-39OC PL602-39OC-R PL620-00DC PL620-20DC PL620-20WC PL620-21DC PL620-30DC PL620-80DC PL620-88OC PL620-88OC-R PL680-30DC PL680-39QI PL680-39QI-R PL130-05QC PL130-05QC-R PL130-07AOC PL130-07AQC PL130-07AQC-R LIAL-01RFYA098 - End of Life (EOL) of PL130, PL502, PL520, PL580, PL602-00/03/04/11/3x, PL620 and PL680 Micrel device families

PL130-07QC-R PL130-07SC-R PL130-07SI-R PL130-07SI-R PL130-08OI PL130-08OI-R PL130-09QC-R PL130-09QC-R PL130-09QI-R PL130-09QI-R PL130-09SC-R PL130-09SS