


Light is OSRAM

Not For New Design OS-NFND-2021-021

02 August 2021

Expected discontinuation date:	1-5 Years
Reason:	The following products have reached their end of life.
OSRAM OS Expectations:	Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
SFH 4796S	Q65112A0372	OSLUX	01.12.2023	SFH 4717AS	Q65112A1517	OSLON
SFH 4756S	Q65113A0217	OSLUX	01.12.2023	SFH 4727AS	Q65112A1144	OSLON