



PCN - 11 017

Issue Date: March 24 2011

Product Name:	D-sub components standardisation			
	All duplicate D-sub accessory part numbers from multiple sources and FCI manufacturing sites will be consolidated.			
Product Manager:	Anup K.P.			
Subject:	Product Change Notification			
Distribution:	Global			
Type of Change:	Product Design Change			
Change Description:	<p> A B C D E F </p> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="border: 1px solid black; padding: 2px; width: 15%;">Fillister type Screw head</div> <div style="border: 1px solid black; padding: 2px; width: 25%;">i) Absence of Screw driver slots ii) Part identification marks standardized</div> <div style="border: 1px solid black; padding: 2px; width: 20%;">Absence of Souriau logo</div> <div style="border: 1px solid black; padding: 2px; width: 20%;">Die cast component replaced by stamped component</div> <div style="border: 1px solid black; padding: 2px; width: 20%;">Dim A standardized to 5.0 mm Material changed to steel</div> </div>			
Reason for Change:	To improve the efficiency of supply ranging from piece part management to the finished goods shipment there by reducing the end connector Leadtime.			
Affected Parts:	As per file attached			
Effective Date of Change:	April	24	2011	
Last Time Buy Date:	N/A	N/A	N/A	
Last Disty Return Date:	N/A	N/A	N/A	
Datasheet Attached?	No			
Qual/Test Data Attached?	No			
Samples Availability Date:	March	18	2011	
Available Alternatives?	No			
Questions?	<i>Contact your local FCI Representative, or</i>			
	<i>Anup K.P.</i>			
	<i>00.91.484.6611582; anup.k-p@fci.com</i>			