



Date Issued: 12-May-2022

## End of Life Notification EOL 22.008

This document is an End of Life (EOL) Notification for the following QSFP+ 40G LR4 transceivers.

### Affected Part Numbers and Recommended Replacement Part Numbers:

The II-VI part numbers affected by this EOL notice, and the corresponding replacement part numbers (if exist) are as following:

EOL P/Ns	Description	Replacement P/Ns
FTL4C1QE2C(-xx)	40G LR4 C-temp	FTL4C1QE3C(-xx)
FTL4C1QE2L(-xx)	40G LR4 Reduced temp	FTL4C1QE3L(-xx)
FTL4C1QL2C(-xx)	40G LR4 Lite C-temp	FTL4C1QL3C(-xx)
FTL4C1QL2L(-xx)	40G LR4 Lite Reduced temp	FTL4C1QL3L(-xx)
FTL4C1QM2C(-xx)	40G LR4 Multi Rate C-temp	N/A
FTL4C1QW2N(-xx)	40G LR4 Extended temp	N/A
FTL4C2QE2C(-xx)	40G LM4	FTL4S1QE2C(-xx)*
FTL4C3QE2C(-xx)	40G LM4/Universal	N/A

\* For 40G LM4, the replacement PN is 40G SWDM4 FTL4S1QE2C. LM4 and SWDM4 operate at different wavelengths, and therefore are not interoperable. Both support 40G transmission over multimode fiber, and SWDM4 has longer reach and lower power consumption.

### Reason for Discontinuation

This product is being discontinued because a DC/DC converter IC used in it has been discontinued by its supplier.

### End of Life Dates

This EOL Notification is effective immediately. II-VI is not taking Last Time Buy (LTB) orders due to the IC shortage.

### RMA Replacements

II-VI reserves the right to replace any of the discontinued QSFP+ 40G LR4 transceiver products listed above returned under RMA (Return Material Authorization) with the equivalent replacement parts, or with a credit, if it is deemed to be II-VI's responsibility.



II-VI Incorporated  
375 Saxonburg Boulevard  
Saxonburg, PA 16056

## List of Supporting Materials

Product Verification Test (PVT) and Reliability Qualification Test Report (QTR) for the replacement products are available upon request.

For More Information, please contact your local II-VI representative, or

II-VI Incorporated  
375 Saxonburg Boulevard  
Saxonburg, PA 16056  
[Photonics.sales@ii-vi.com](mailto:Photonics.sales@ii-vi.com)  
[www.ii-vi.com](http://www.ii-vi.com)