



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M001042A

DATE: 21-Sep-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	IH5341EWE+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4391ESA+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4531CWP+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4540EAP+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX5003CSE+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX5003ESE+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX634CSA+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX634ESA+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX638AESA+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-Oct-2021