



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001020I

DATE: 15-Dec-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1087LU-466+T&R	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	DS1233M-5+T&R	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	DS1707EUA+T&R	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	ICL7641ECWE+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX111129ATI+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1179BCUI+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX14526DEEWP+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX14566BEETA+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX14934DAWE+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX14934DAWE+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX15048ETJ+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX1508YETA+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1567ETL+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1912EUB+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX1963AEZT100+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX394CAP+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX4481AXT-T	MAX4481AXT+T	15-Mar-2021	13-Jun-2021	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4754AETE+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5052AEUA+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5417PETA+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5491SA03200+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5900ACETT+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX5955BUUEE+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX6306UK44D2+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6308UK00D1+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6386XS31D5+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Jan-2021

Discontinuance	MAX6413UK16+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6424UK22+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6456UT46S+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6469TA28AD3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6710MUT+T	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6735KASVD3+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6825TUK+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX6827RUT+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX7418CUA+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX77829EWN+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8648ETE+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8680ETL+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX8877EZK42+GF4	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured
Discontinuance	MAX9393ETJ+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX9728BEUD+	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX9877EWP+G45	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MAX9929FABT+G45	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MX7537LCWG+T	N/A	15-Mar-2021	13-Jun-2021	Part can no longer be manufactured
Discontinuance	MXD1815XR29+	N/A	10-Dec-2021	08-Jun-2022	Part can no longer be manufactured