

Product Change Notification - SYST-19SWVB462

Date:	23 Oct 2017
Product Category:	Driver / Interface ICs
Affected CPNs:	 
Notification subject:	Data Sheet - HV5622 32-Channel Serial-to-Parallel Converter with Open Drain Outputs Data Sheet
Notification text:	SYST-19SWVB462

Microchip has released a new DeviceDoc for the HV5622 32-Channel Serial-to-Parallel Converter with Open Drain Outputs Data Sheet of devices. If you are using one of these devices please read the document located at [HV5622 32-Channel Serial-to-Parallel Converter with Open Drain Outputs Data Sheet](#).

Notification Status: Final

Description of Change: 1) Converted Supertex Doc # DSFP-HV5622 to Microchip DS20005854A. 2) Removed "Processed with HVC MOS[®] Technology" in the Features section. 3) Changed the package marking format. 4) Removed the 44-lead PQFP PG M919 and 44-lead PLCC PJ M903 media types. 5) Made minor changes throughout the document.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 23 Oct 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [HV5622 32-Channel Serial-to-Parallel Converter with Open Drain Outputs Data Shee](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

HV5622PJ-G

HV5622PG-G

HV5622K7-G-S343