

## **Global Change Notification (GCN)**

**Product Family** MX150 10678251 **GCN Number** Series Various April 17, 2015 Date Issued Reason For Change New, Modified, Or Replacement Tooling Change Description This letter is to announce that Molex is building 4 new dies to make MX150 terminals. The dies will make MX150 Receptacle Cable Seal, MX150 Receptacle Mat seal & MX150 Blade mat seal Terminals. The dies are being built to allow Molex to better accommodate customer demand. MX150 Male terminal MX150 Female Terminal Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception **New Capacity** Assessment Of Change Product from the new dies will be fully qualified before it is released to (How Product Will Be Qualified & Validated) production. PPAPs are available upon request on June 5, 2015. Internal Molex Qualification Date June 05, 2015 (Planned Date Information Available) Sample Availability Date June 05, 2015 (Changed Part) Date of Implementation June 05, 2015

Product made after June 5, 2015 can be from the new dies.

Not Applicable

Method of Identifying Change

Recommended Replacement Parts

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com