

# Nidec Copal Electronics Corp.

Sensor Division

Aakami 2188, Sano, Tochigi, 327-0104, Japan

Tel : +81-283-25-3111

---

---

September 3, 2021

## Product Discontinuance Notification

Dear valued customers

This is to inform you formally that the following products are being discontinued. This notification is for your company to take appropriate action should your internal documentation for these part numbers need to be updated.

### **【Products affected】**

Product Name	Discontinued Part	Suggested Replacement*
Pressure Transducers	PA-870-203P-B-R2 PA-870-203P-H-R2 PA-870-353P-B-R2 PA-870-353P-H-R2 PA-870-503P-B-R2 PA-870-503P-H-R2 PA-878-203P-B-R2 PA-878-203P-H-R2 PA-878-353P-B-R2 PA-878-353P-H-R2 PA-878-503P-B-R2 PA-878-503P-H-R2	PA-75 series or PA-86
Pressure Switches	PS87-353P-B-R2 PS87-353P-H-R2 PS87-503P-B-R2 PS87-503P-H-R2	None

### **【Reason for change】**

Due to the aging of the diaphragm mold, it is difficult to continue to manufacture those pressure sensors.

### **【Effective date】**

Last Order Acceptance : February 28, 2022.

Last Time Shipments : August 31, 2022.

Should you have any questions, please contact your local sales representative/office for more details.